Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Cecilia Lee	Date:	10 May 2023

Preliminary Advice

Insured Vehicle No	: GBE746G		
TP Vehicle No	: SLL1973E	Accident Date	: 27/02/2023
Make	: TOYOTA CAMRY	Assignment Date	: 28/02/2023
Date of Inspection	: 28/02/2023	Est. Duration of Repair	: 8 DAYS
Inspection At	: EM SOLUTION PTE LTD		

Point of Impact / General Description of Damages

Parts claimed consistent to the accident.

Repairer's Estimate (Gross)	:S$	16,977.69
Revised Amount	:S$	11,408.07
Check Items (Estimated)	:S$	0.00
Total	:S$	11,408.07
Lump Sum Repair	:S$	9,100.00

Total Loss Consideration

New for Old Value	:S$
Pre-Accident Value	:S$
COE / PARF Rebate	:S$
Salvage Value	:S$
Margin for Repair	:S$

Remarks

( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : The above survey was conducted on a 'Without Prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour costs.