Progressive [illegible] Pte Ltd

Blk 3022A Ubi Ro[illegible] [illegible]pore 408716
TEL: 6741 5336 FAX: [illegible] [illegible]@procarcare.com.sg
GST:201[illegible] [illegible]06949C

M/S : SOMPO INSURANCE SINGAPORE PTE. [illegible]
50 Raffles Place
Singapore Land Tower #05-01/06
Singapore 048623
TEL: 64616555 FAX: 62213[illegible]
ATTN: Motor Claim Department \ SOMPO

[illegible] Car Care [illegible]
[illegible] #01-45/46 Singa[illegible]
[illegible] 7208 Email: claim[illegible]
[illegible]06949C RCB NO:2010[illegible]

Estimate No:	**EST1509318**
Date:	13 Apr 2023
Policy No:	P10266655R03
Veh Reg No:	**SLH1697Z**
Make/Model:	NISSAN X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Chassis No:	JN1JANT32Z0002647
Engine No:	MR20904251B
Reg. Date:	26/10/2016

Your Ref No:	TP 0223-7260
Claim Type:	Third Party
Accident Date:	10/02/2023
TP Veh Reg No:	SFU6556S

Estimate Repair Cos[illegible] [illegible]'cle No :SLH1697Z

	Description	U/Price	Quantity	Price S$	Amount S$
	Supplementary Parts to Repair				
	List Price	0$196.60			
1	REAR BUMPER REINFORCEMENT BRACKET - LH/RH	~~196.6000~~	2 PC Set	393.20	
				393.20	
			Less 10%	39.32	353.88
				Total	S$ 353.88
				GST Amount	S$ 28.31
				Total Amount Payable	S$ 382.19

[illegible] **For Progressive Car Care Pte Ltd**

AUTHORISED SIGNATURE

SUPP	353.88
PARTS	5394.42
SN	200.00
LAB.	1330.00
	7278.30.

4/5: 5800