



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Ref: CS/AWA22008778/Ecy3e2-1 Date: 24/03/2023 Code: AWA	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.	XE 6903U	Veh. Inspected	RIGID TANKER
Policy No.	BVFCB0007172215	Coverage (\$)	70,000.00
Claim No.	NSV2200131/PC	Excess (\$)	0.00
Assign From	GOH STELLA	Assign Date	06/09/2022
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	Year of Reg.		
Chassis No.	Colour		
Odometer	Steering		
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
THE RIGID TANKER SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/08/2022	Inspection Date	13/09/2022
Survey held at	24 JALAN BUROH SINGAPORE 619480		
Repairer	SSB CRYIGENIC EQUIPMENT PTE LTD		
5a. Remarks			
A)THE MARKET VALUE IS S\$145,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		25 Working Days	

SSB CRYOGENIC EQUIPMENT PTE LTD

<u>Qty</u>	<u>Description</u>	<u>Condition</u>	<u>Estimate</u>	<u>Recommendation</u>
1	Lot Tank survey	Necessary	\$ 300.00	\$ 300.00
1	Lot Break vacuum for welding works	Necessary	\$ 300.00	\$ 300.00
1	Pcs Replacement of diversion valve	Necessary	\$ 2,000.00	\$ 2,000.00
2	Pcs Replacement of flexible hose	Bent	\$ 600.00	\$ 600.00
1	Lot Manpower charges for Replacement of pump (AL supply)	Necessary	\$ 500.00	\$ 500.00
1	Pcs Replacement of vacuum probe (Hasting) (DV-6R)	Necessary	\$ 250.00	\$ 250.00
1	Lot Installation of piping support with welding works	Necessary	\$ 600.00	\$ 600.00
4	Pcs Replacement of Herose SRV (3 bar)	Necessary	\$ 3,600.00	\$ 3,600.00
1	Lot Refurbish of pipeline for ISO Tank	Necessary	\$ 3,000.00	\$ 3,000.00
1	Lot Refrabrication of ventline	Necessary	\$ 2,000.00	\$ 2,000.00
1	Lot Purging of ISO tank (LIN) & pressure test	Necessary	\$ 1,000.00	\$ 1,000.00
1	Lot Vacuum pulling	Necessary	\$ 2,000.00	\$ 2,000.00
4	Pcs SRV pop testing with in-house Certificate	Necessary	\$ 150.00	\$ 150.00
1	Lot Canopy repairs	Dented	\$34,000.00	\$34,000.00
1	Lot Sandblasting and painting of ISO tank	Necessary	\$ 2,500.00	\$ 2,500.00
1	Lot Testing and commission of road tanker	Necessary	\$ 1,000.00	\$ 1,000.00
1	Lot BV recertification	Necessary	\$ 1,500.00	\$ 1,500.00
			Total (A) :	\$55,750.00 =====

RPM ELECTRICAL ENGINEERING PTE LTD

<u>Labour Charges</u>	<u>Estimate</u>	<u>Recommendation</u>
1) Supply skilled labour and necessary instruments to disconnect power and control cable, dismantle out for repair c/w rewiring after completion	\$5,580.00	\$5,580.00
Job include material supplied as follows:-		
a) Emergency Push Button, CSE121209P/WPBERR0 – 1pc		
b) S/S enclosure 700 x 500 x 250mm – 1pc		
c) Neoprene cable 4C x 16mm ² - 17meters		
d) 4-Pin 63Amp plug – 1pc		
e) Change over switch 63A/4pole (A619) – 1pc		
f) Metal angle bar/flat bar (bracket for cable storage enclosure)		
	Total (B) :	\$5,580.00



AIR LIQUID SINGAPORE PTE LTD

<u>Qty</u>	<u>Description of Parts</u>		<u>Estimate</u>	<u>Recommendation</u>
1	Overfilling Trailer Protection	USD	\$1,400.00	\$1,400.00
1	DAP Singapore	USD	\$ 170.00	\$ 170.00
			USD	<u>\$1,570.00</u> =====

USD convert to SGD at 1.42 as at 14/10/2022 of invoice

\$2,229.40
=====

Note: The repair done by RPM Electrical Engineering Pte Ltd

<u>Qty</u>	<u>Description of Parts</u>	<u>Condition</u>		<u>Estimate</u>	<u>Recommendation</u>
1	GBS 155/4,5 Part No: CEP02GEN	Broken	EUR	\$11,501.00	\$11,501.00
				EUR	<u>\$11,501.00</u> =====

EUR convert to SGD at 1.39 as at 29/08/2022 of invoice

\$15,986.39
=====

Note: The repair done by SSB Cryogenic Equipment Pte Ltd

Total (C) : **\$18,215.79**
=====

Recommended Cost of Repair (Rigid Tanker) (A + B + C)	\$79,545.79
Less Owner's Contribution	- \$ 9,545.79
Nett Liability	\$70,000.00 =====

(SIN DOLLARS: Seventy Thousand Only)

We recommend that the repairs of the entire damage require about 25 (Twenty-Five) working days to complete.

Vehicle Inspected By:



CHEN TSUE YEE
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. RIGID TANKER

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. RIGID TANKER

RE-INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. RIGID TANKER

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. RIGID TANKER

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. RIGID TANKER

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





新瑞美低温设备私人有限公司
SSB CRYOGENIC EQUIPMENT PTE LTD

No. 6 Attap Valley Road Singapore 759906 Tel: (65) 6752 2711 Fax: (65) 6752 2071
E-mail: info@ssb.com.sg Website: www.ssb.com.sg
Company Registration No.: 199609144C

QUOTATION

To: **ALLIED WORLD ASSURANCE LTD**

From: **Andrew Lim**

Attn:

Date: **28th February 2023**

Phone:

Ref. No.: **Q0922/AL/266R3**

Email:

Pages: **1 page only**

Below are the LN 0710 ISO tank repair cost for your approval:

Item	Description	Qty	Unit	Unit Price	Total
	LN 0710 ISO Tank Repair				
1	Tank survey	1	Lot	SGD 300.00	SGD 300.00
2	Break vacuum for welding works	1	Lot	SGD 300.00	SGD 300.00
3	Replacement of diversion valve	1	Pcs	SGD 2,000.00	SGD 2,000.00
4	Replacement of flexible hose	2	Pcs	SGD 300.00	SGD 600.00
5	Manpower charges for replacement of pump (AL supply)	1	Lot	SGD 500.00	SGD 500.00
6	Replacement of vacuum probe (Hasting)(DV-6R)	1	Pcs	SGD 250.00	SGD 250.00
7	Installation of piping support with welding works	1	Lot	SGD 600.00	SGD 600.00
8	Replacement of Herose SRV (3 bar)	4	Pcs	SGD 900.00	SGD 3,600.00
9	Refurbish of pipeline for ISO tank	1	Lot	SGD 3,000.00	SGD 3,000.00
10	Refrabrication of ventline	1	Lot	SGD 2,000.00	SGD 2,000.00
11	Purging of ISO tank (LIN) & pressure test	1	Lot	SGD 1,000.00	SGD 1,000.00
12	Vacuum pulling	1	Lot	SGD 2,000.00	SGD 2,000.00
13	SRV pop testing with in-house certificate	4	Pcs	SGD 150.00	SGD 600.00
14	Canopy repairs	1	Lot	SGD 34,000.00	SGD 34,000.00
15	Sandblasting and painting of ISO tank	1	Lot	SGD 2,500.00	SGD 2,500.00
16	Testing and commission of road tanker	1	Lot	SGD 1,000.00	SGD 1,000.00
17	BV recertification	1	Lot	SGD 1,500.00	SGD 1,500.00
Total					SGD 55,750.00
8% GST					SGD 4,460.00
Grand Total					SGD 60,210.00

Terms and Conditions:

Validity : 7 days after the date of the quotation.

Price : In SGD Dollars

Payment Terms: 100% after the date of the invoice. Cancellation is not allowed once the order is placed.

Note: - Discounts are not entitled for main parts and replacement parts, unless otherwise specified.
- Other spares which are not stated in the above quotation shall quote separately if found replacement is needed after the tank survey.

Yours truly,

SSB CRYOGENIC EQUIPMENT PTE LTD

Name: Andrew Lim

Mobile: +6583829654

Email: andrew@ssb.com.sg

Regional Sales Executive

Confirmed and Accepted by

Authorized Signature & stamp



RPM ELECTRICAL ENGINEERING PTE LTD

No. 1 Joo Koon Way, Gate 2, Singapore 628942

Tel: 6862 0560 (5 lines) Fax: 6861 2980 Email: rpmeep1@singnet.com.sg

Website: <http://www.rpmElectrical.com.sg>

Mailing Address: Jurong Point Post Office, PO Box 485, Singapore 916417

Company Reg. No: 200409160K GST Reg. No: 20-0409160-K

TAX INVOICE

ALLIED WORLD ASSURANCE COMPANY LTD

(SINGAPORE BRANCH)

60 Anson Road, #08-01 (8th floor)

Mapletree Anson

Singapore 079914

Attn : Finance Dept

Tel :

Fax :

A/C No : 3005/A10

DELIVER TO :

AIR LIQUIDE SINGAPORE PTE LTD

J-3 Supply Chain Dept

Attn : Mr Andy Chan

Tel : 9336 9735

INVOICE NO. : 2321822

DATE : 28/02/2023

D/O NO. : -

P/O NO. : -

OUR REF : QP/22-1489

JOB NO. : 1569/22

TERM : Cash

AGENT. : PC

PAGE : 1

Item Description	Qty	Unit Price	Amount
Insured Veh. XE 6903U, LN 0710 Policy No. Claim No.			
1 Supply skilled labour and necessary instrument to disconnect power and control cable, dismantle out for repair c/w rewiring after completion Job include material supplied as follows:- a) Emergency Push Button, CSE121209P/WPBERR0 - 1pc b) S/S enclosure 700 x 500 x 250mm - 1pc c) Neoprene cable 4C x 16mmsq - 17 meters d) 4-Pin 63Amp plug - 1pc e) Change over switch 63A/4pole (A619) - 1pc f) Metal angle bar/flat bar (bracket for cable storage enclosure)	1 Unit	5580.00	5580.00
Attachment: Service Report			

SINGAPORE DOLLAR : SIX THOUSAND TWENTY SIX AND CENTS FORTY ONLY

SALES AMOUNT	5,580.00
SUB TOTAL	5,580.00
GST 8 %	446.40
TOTAL AMOUNT S\$	6,026.40

AUTHORISED SIGNATURE(S)

All cheque should be crossed and made payable to:

RPM ELECTRICAL ENGINEERING PTE LTD




Air Liquide Singapore Pte Ltd
New Rigid Tanker XE 6903U, LN 0710

Job No : 1569 / 22

Date : 12 Oct, 2022

Disconnection Power / control cable, Dismantle out some parts for repairing
 tanker canopy and Install back with rewiring after done repair

Job Scope

PICTURES of Job scope before dismantle	
	
P1. Condition of tanker for job carry out	P2. All the necessary cable need to disconnect for repairing tanker canopy including from motor control panel
	
P3. Anti TOW Limit switch need to dismantle out & rewiring after done repair job	P4. Motor power cable need to disconnect out & rewiring after done repair job
	
P5. Flow meter need to dismantle out / disconnect cable & install back / rewiring after done repair job	P6. EX proof light need to dismantle out / disconnect cable & install back / rewiring after done repair job

Air Liquide Singapore Pte Ltd

New Rigid Tanker XE 6903U, LN 0710

PICTURES of Job scope before dismantle

	
P7. EX proof on-off switch for light need to dismantle out / disconnect cable & replace with new / rewiring after done repair job	P8. Motor remote on /off switch & valve control air switch need to dismantle out / disconnect cable & install back (May be need to repair) / rewiring after done repair job
	
P9. Over Fill Protection for valve control box need to dismantle out & install back with new after done repair (Need to provide us new Over Fill Protection Control)	P10. Power cable storage enclosure with bracket need to dismantle out & install back with new after done repair job
	
P11. Change over switch also need to chang from cable storage enclosure	

Summary of Job Scope

1. Anti TOW Limit switch need to dismantle out & rewiring after done repair job
2. Motor power cable need to disconnect out & rewiring after done repair job
3. Flow meter need to dismantle out / disconnect cable & install back / rewiring after done repair job
4. EX proof light need to dismantle out / disconnect cable & install back / rewiring after done repair job
5. EX proof on-off switch for light need to dismantle out / disconnect cable & replace with new / rewiring after done repair job
6. Motor remote on /off switch & valve control air switch need to dismantle out / disconnect cable & install back (May be need to repair) / rewiring after done repair job
7. **Over Fill Protection** for valve control box need to dismantle out & install back with new after done repair
8. Power cable storage enclosure with bracket need to dismantle out & install back with new S/S enclosure with new bracket after done repair job
9. Change over switch also need to chang from cable storage enclosure

Material supplied

- | | | |
|---|----|------|
| 1. EX Proof On-Off switch 10 Amp | 1 | pc |
| 2. Stainless Steel Enclosure 700 x 500 x 250 mm | 1 | pc |
| 3. Neoprene cable 4C x 16mm ² | 17 | mtrs |
| 4. 63 Amp, 4 pin plug | 1 | pc |
| 5. Change Over Switch 63 Amp, 4 pole (A 619) | 1 | pc |
| 6. Metal Angle bar / Flat bar (Bracket for Cable storage enclosure) | 1 | Lot |

Remark

Need to provide us new Control box for Tank Over Fill Protection