PRS Rec. By: GQ REF: CS3/SMR22010711/Dwy3-1

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / N/S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s TUNE IN MOTOR

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S O/S

Bal. or Market Value: $13k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBS7584L Yr Regn: 23 Jul/2021

Type: M.Car M.Cycle Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: YAMAHA T155 c.c 155

Colour BLUE A/C: Insured / Std / NI / NA

Sp.Reading — T/Radio: Insured / Std / NI / NA

Eng/No: G3R9E001192

C/No: RLCUG1610MY001195 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 80/90-17

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	mm	L/Bal.	mm

D.O.A. 22-10-2022 D.O.I. 28-10-2022

Survey held at W/S 3:30PM

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	$2000 - $3000
07/03/2023	Submit L/S $1,550.00 @ 03 days (Red $1,950.00/ 56%)

Date/Time, File Pass to? 07/03/2023 1) Typist

Date/Time, File Return to? 2)

☐ : Preli. Report

☑ : Final Report

Days Of Repair: 03

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format : TP

Lump Sum / UPR : L/S $1,550.00

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL