ASS. REC. BY: Steve CS3/ASM7/2009795/Ery3

ASSIGNMENT

From: PRS Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SHC 7393J

Policy No.

Claims No. S2M04C3L

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SFT3694 Yr Regn: 18/7/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Freed c.c 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading 41033 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GB710 84187

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Kapsen

Front		Rear	
R/Bal.	4 mm	R/Bal.	4 mm
U/Bal.	4 mm	U/Bal.	4 mm
D.O.A.	30/9/22	D.O.I.	4/10/22

Survey held at Lay Auto

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV-109K Repair range 4K-5K 8 days
21/10/22	Submit PRS, repair range ~~$4,000-$5,000~~

Date/Time, File Pass to?

1) : Preli. Report

: Final Report

Date/Time, File Return to?

2) 21/10/22-typist

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair: 8

Resurvey No. of Trip:

Add Fee: : Site Insp ($)

: Interview ($)

: Tech. Invs ($)

: Weekend ($)

Survey Fee:

Transportation:

$ + RS. S

Photos

Others

TOTAL