EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C
#01-68 SINGAPORE 575643
Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)
Email Address: em1autopteltd@gmail.com
COMPANY / GST REG. NO. : 201316380R

Vehicle Number :	**SLQ 6073T**	**Date :**	**13.03.2023**
Vehicle Model :	**TOYOTA WISH ELEGANCE**	**Chassis :**	**JTDGG20W90J007551**
Accident Date :	**10.03.2023**	**TP Ins.**	**LIBERTY**
Original Reg Date :	**17.07.2017**		

SKV 1111 K (BYD E6)

ESTIMATE

1	1 pc	Tailgate Assy		bt	1,373.50	
2	1 pc	Tailgate Badge		new	65.00	
3	1 pc	Tailgate Emblem VALVE MATIC		new	80.00	
3	1 pc	Tailgate Emblem ELEGANCE		new	76.00	
4	1 pc	Tailgate Outer Chrome Moulding - Photo		cut	385.00	
5	1 set	Tailgate Outer Chrome Moulding Clips		new	30.00	
6	1 pc	Tailgate Opener Switch		Ong	186.20	
7	2 pcs	Tailgate Number Plate Lamps	85.00	Ong	170.00	
8	1 set	Tailgate Windscreen Moulding		new	169.50	
9	1 set	Tailgate Windscreen Clips		new	25.00	
10	1 pc	Tailgate Wiper Motor		X nn	685.90	
11	2 pcs	Tailgate Lamps Assy @ 366.20	560.00	Ong	1,120.00	
12	2 pcs	Tailgate Lamps Sealer	40.00	X nn	80.00	
13	2 set	Tailgate Lamps Clips	25.00	new	50.00	
14	1 pc	Tailgate Pocket Handle		X nn	49.50	
15	1 pc	Tailgate Inner Trim		Ong	429.80	
16	1 set	Tailgate Inner Trim Clips		new	40.00	
17	2 pcs	Tailgate Stopper	24.00	X nn	48.00	
18	1 pc	Tailgate Inner Lock		ht/paint	448.00	375
19	1 pc	Tailgate Auto Lock Actuator		Ong	195.50	
20	1 pc	Tailgate Lock Catch		X nn	78.00	
21	1 pc	Tailgate Weatherstrip		kui	320.00	
22	2 pcs	Tailgate Hinges	85.00	Ry	170.00	
23	2 pcs	Tailgate Absorber	220.80	Ry	441.60	
24	1 pc	Rear Bumper		dl	725.00	684
25	2 pcs	Rear Bumper Side Retainers	58.00	de	116.00	
26	2 pcs	Rear Bumper Attachement Retainers	42.00	de	84.00	
27	1 set	Rear Bumper Clips		new zo	50.00	
28	2 pcs	Rear Bumper Dampers	78.00	ht	156.00	
29	2 pcs	Rear Bumper Reflector Lamps	82.00	X nn	164.00	
30	2 pcs	Taillamps Assy @ 566	620.00	Ong	1,240.00	
31	2 pcs	Taillamps Sealer	40.00	X nn	80.00	
32	2 set	Taillamps Clips	25.00	X new	50.00	

C/F **9,381.50**

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C
#01-68 SINGAPORE 575643
Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)
Email Address: em1autopteltd@gmail.com
COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLQ 6073T **B/F** **9,381.50**

1	1 pc	End Panel Assy plate		bt —	672.50
3	1 pc	End Panel Top Trim		dl —	285.00
4	1 set	End Panel Top Trim Clips		ul —	30.00
5	1 pc	Rear Floor Panel Top Board		dl —	385.00
6	2 pcs	Rear Fender Inner Trim @679	798.00	Cw	1,596.00
7	2 set	Rear Fender Inner Trim Clips	30.00	ul	60.00
8	1 pc	Spare Tyre Carrier		x mm	356.20

597

1pc Spare Tyre Panel Top Inner Garnish $356.10 cm 12,766.20

Less 25% 3,191.55

9,574.65

Special Nett

1	1 set	Reverse Sensor		200 mm	250.00
2	1 pc	Rear Windscreen Sealant		ul —	60.00
3	1 pc	Tailgate Windscreen Inner Seal		ul —	60.00
4	1 set	Body Panel Joint Sealant		50 u —	120.00
5	1 set	Rear Floor Panel Insulator Pad		x mm	150.00
6	1 pc	Rear Number Plate with Cover		bt — 15	70.00

Labour charge

Panel Beating		800	1,200.00
Spray painting		900	1,000.00
Check Wiring		30	50.00
Anti rust		30	100.00
Remove and install rear windscreen.		120	140.00
Remove and install tailgate parts.		60	90.00
Remove and install carpet and seat		60	120.00
Remove and install reverse sensor		30	90.00

13,074.65

Less 20% 2,614.93

Lump sum **10,459.72**

Tanghin 97495719
wp 14/3/23 @ 1430
c/s Resurvey after repair
o 7days
tanghin @ lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: