C. BY: Kenneth

REF: TW / 23002823/K
GRB

Date:

Estimated Cost:

WS / TP RES / OD RES / EVA / INV / MV

Suspect Vehicle No:

Workshop m/s: Optime

Insured:

Policy No.

Claim No.

Sum Insured: Excess:

(Insurer's Record)

Market Veh:

1pm

(Vehicle Condition)

The veh had commenced its repair at the time of Inspection. N/S

Balance Market Value: ₱70k

ICAR Accident Report: Consistent? : Yes or No

GIA Report Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle:

Date / Time	Action / Instruction
1)	
2)	

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Prell. Report

☐ : Final Report

Report format :

Lump Sum / I.B.I: ($)

Add Fee:

Date of Trip:

Date Insp ($)

Interview ($)

Photos ($)

Total ($)

Survey Fee

Transportation

$ - RS.

Others

TOTAL

N ENT

Plate No: Sim 8048A Year: 04 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Trailer or

Toy Prius (A) 1798

Colour: M. Grey A/C: NA

Engine: 323117 T/Radio: NA

Chassis No: JTDKB3FU703541320

Exterior Cond: Good / Fair / Poor / Burnt

Interior / Jammed / Leaked / Burnt or

Interior / Jammed / Leaked / Burnt or

Wheel: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55ZR16

R:

EXNOVA / GY / FS / LIZA / MIC / OHT

TOKO or Intertrac

Gear

9 mm F/Bal. 9

9 mm R/Bal. 9

17/3/23 D.O.I. 21/3/2023

Damages : Frt / Rear / O/S / N/S / U/C

Rear N/S

Chassis frame / Body Structure affected