INIT'Y: Sms

ASS. REC. BY:

REF: CS/TMI23002955/Svy3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SJP 7532H TMI

Policy No. MS008156

Claims No. M2301823

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Rea: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHC 1079G Yr Regn: 09/08/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Hyundai Ioniq c.c 1580

Colour: Blue A/C: Insured / Std / Nil / NA

Sp.Reading: 616476 T/Radio: Insured / Std / Nil / NA

Eng.No:

C/No: kmh C85 C CKU 10 6514

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Intact / Jammed / Leaked / Burnt or

Brake: Intact / Jammed / Leaked / Burnt or

Mod: NB / S/Rim / STD Rim or

Tyre Size: F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Westlake

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	19/3/23	D.O.I.	22/3/23 2pm

Survey held at: Comfort.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	L/S =
27/3/23	Irfan confirmed LS $1150 (red 3432.44, 74%)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 27/3/23-typist

: Prell. Report

: Final Report

Report Format: Merimen

Lump Sum / L.B.I: ($ 1150)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: : Site Insp ($)

: Interview ($)

: Tech. Invs ($)

: Weekend ($)

Survey Fee:

Transport:

S + RS

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline • 65 6383 6280 Facsimile • 65 6280 8755
Workshops
59 Loyang Drive Singapore [illegible] | 24 Senoko Loop Singapore [illegible]
383 Sin Ming Drive Singapore 575717 | 7 Sungei Kadut Way Singapore [illegible]
45 Pandan Road Singapore [illegible] | 501 Yishun Industrial Park A Singapore [illegible]
[illegible]

Date/Time: 20.03.2023 13:56 Page : 1

eam: · ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5890042 JC NO305549202

STOMER

MS COMFORT TRANSPORTATION PTE LTD
STOMER NO. 7010045
RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

COUNT CARD NO.

REGN NO.: SHC1079G	MILEAGE
MAKE: HYUNDAI	FUEL E 1/2 F
MODEL IONIQ(G2)	DATE/TIME IN 19.03.2023 13:55
YR OF MANU. 09.08.2018	TARGET DATE
CHASSIS CODE KMHC851CVKU106514	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 19.03.2023
ATURE: 3P 19.03.2023

/NO	LABOR CODE	DESCRIPTION
000010	PB	PANEL BEATING-SHC1079G-TP
000020	23-01	TOWING FEE



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wledgement Slip

:

No.: SHC1079G LIMTS

of Service Advisor

Signature/Date

eturned to Service Reception upon collection

Exit Pass

Vehicle No.: SHC1079G

Name of Service Advisor

Date

To be kept by Security Guard

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

6553 1111
SPARK Assist

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

1. Date: 19/03/2023 Time Received: 13.55

2. ☐ New ☐ SPARK Kakis

Name of Customer : LEE KOK THYE

Contact No. : 96398860

Vehicle No. : SHC 1079G

Make / Model / Colour :

Email :

3. Vehicle Type:
- ☐ Private
- ☑ Taxi (CTPL/CCPL)
- ☐ Fleet
- ☐ STK (Boon Lay)

4. Type of Towing:
- ☑ Normal Tow
- ☐ King Dolly
- ☐ Flat Bed
- ☐ Crane-up

5. Nature of Service:
- ☐ Jumpstart
- ☐ Recovery
- ☐ Change Tyre / Battery

6. Parts Replaced/Remarks:

7. Location: 182 Bedok north rd

8. Vehicle Tow - In Workshop:
- ☐ Smoky Exhaust
- ☐ Overheating
- ☐ Brake Faulty
- ☐ Starting Problem
- ☑ Accident
- ☐ Return Taxi
- ☐ Wheel Jammed
- ☐ Steering Faulty
- ☐ Alternator Faulty
- ☐ Loss Power
- ☐ Engine Stalled

9. Preferred Workshop:
- ☐ Braddell
- ☐ Sin Ming
- ☐ Komoco (UBI / Leng Kee)
- ☐ Others:
- ☑ Loyang
- ☐ Sungei Kadut
- ☐ Pandan
- ☐ Ubi
- ☐ Cycle & Carriage (PD)

10. Odometer Reading :

Fuel Level : F | 1/4 | 1/2 | 3/4 | E

11. Radio / CD Player
- ☐ OK
- ☐ Faulty
- ☐ Not tested



: Cracked X : Dented
/ : Scatched O : Missing

Signature of Customer

Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☐ QA ☐ GAO ☐ OTHERS

Name of Driver : SAM CHEE

Vehicle No. : GBS 297 J

Time Dispatch : 13.55 PM

Time of Arrival :

Time Completed :

Cash Invoice Details (if applicable)

13. Cash Invoice No. :

Customer Acknowledgement

a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.

b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.

c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

19/03/2023
Date

1.55 pm
Time

Signature of Customer

14. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

WORKSHOP COPY