DEPT: Emily REF:

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: CTZ

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Sent: _____ Consistent? : Yes or No

Est. Repairs: 7 days Rear: Yes or No

Lum Sum: 20 % 3 Veh: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC102P Yr Regn: 1/8/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / L Truck / Trailer or _____

Make: Hyundai Lorry cc 1580

Colour Yellow A/C: Insured / Std / NI / NA

Sp.Reading 388371 T/Radio: Inspired / Std / NI / NA

Eng No: _____

C/No: KMHC851CVJU103705

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or _____

Brake: Inoper / Jammed / Leaked / Burnt or _____

Modi: NII / S/Rim / STD A/Rim, or _____

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / YOYO / YOKO or westlake

Front		Rear	
R/Bal.	5 mm	R/Bal.	6 mm
U/Bal.	5 mm	U/Bal.	6 mm
D.O.A.	8/3/23	D.O.I.	8/3/23 3pm

Survey held at Comfort

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	L/S

Date/Time, File Pass to? 1) _____

Date/Time, File Return to? 2) _____

☐ : Prell. Report

☐ : Final Report

Report Format : _____

Lump Sum / I.B.I: ($ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Survey Fee:

Transportation:

$ + KS = $

Photos

Others

TOTAL

Scanned with CamScanner

ComfortDelGro Engineering

A member of ComfortDelGro

ComfortDelGro Engineering Pte Ltd
206 Braddell Road Singapore 579701
Mainline : 65 6383 6380 Facsimile : 65 6280 9755
Workshops
69 Loyang Drive Singapore 508968
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609258
24 Benoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 729571
501 Yishun Industrial Park A Singapore

Date/Time: 08.03.2023 14:25 Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 5888703

JC NO305547684

STOMER

/MS CITYCAB PTE LTD
STOMER NO. 7010070
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65551188 (O)
(P)

COUNT CARD NO.

REGN NO.: SHC 102D	MILEAGE
MAKE: HYUNDAI	FUEL E 1/2
MODEL: IONIQ(G2)	DATE/TIME IN 08.03.2023 10:30
YR OF MANU: 01.08.2018	TARGET DATE
CHASSIS CODE: KMHC851CVJU103705	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 08.03.2023
NATURE: 3P 08.03.2023

S/NO LABOR CODE DESCRIPTION



ECKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

wledgement Slip

e No.: SHC 102D CHIANG

of Service Advisor Signature/Date

returned to Service Reception upon collection

Exit Pass

Vehicle No.: SHC 102D

Name of Service Advisor Date

To be kept by Security Guard

Scanned with CamScanner