Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 30 Mar 2023

Preliminary Advice

Vehicle No	: SMQ4584L	Accident Date	: 29/03/2023
Make	: HYUNDAI AVANTE	Policy No.	: SP2004848774
Assignment Date	: 29/03/2023	Excess	: S$600.00
Date of Inspection	: 30/03/2023	Est. Duration of Repair	: 5 days
Inspection At	: SHU FATT AUTO WORKS		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	7,010.90
Revised Amount	:S$	3,570.30
Check Items (Estimated)	:S$	94.60
Total	:S$	3,664.90
Lump Sum Repair	:S$	

Total Loss Consideration

New for Old Value	:S$	
Pre-Accident Value	:S$	13,000.00
COE / PARF Rebate	:S$	5,552.00
Salvage Value	:S$	
Margin for Repair	:S$	7,448.00

Remarks

(x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(x) Other comments : Lump Sum Repair.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.