LIM TAN MOTOR

ESTIMATE TO REPAIR

VEHICLE NO	: QX 1052 R
MAKE	: NISSAN
MODEL	: ELGRAND HIGHWAY STAR 2.5 MC
YEAR	: 2014
CHASSIS NO	: JN1TBAE52Z0802372

SURVEYOR NAME :	
DATE OF SURVEY :	
TIME OF SURVEY :	

DATE	: 06 April 2023
DATE OF ACCIDENT	: 03 April 2023
POLICY NO	: D-23100518MFQC/4
INSURANCE CO	: FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE Singapore 068877

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1pc	front bumper			$ 836.00	
1pc	front bumper reinforcement			$ 969.00	
1pc	front bumper retainer			$ 42.00	
1pc	front grille top			$ 588.00	
1pc	front grille bottom			$ 928.00	
1pc	o/s front bumper fog lamp			$ 355.00	
1pc	o/s front bumper fog lamp cover			$ 310.00	
1pc	o/s head lamp			$ 3,550.00	
1pc	o/s head lamp moulding			$ 99.00	
1pc	o/s front fender inner-shield			$ 89.00	
					$ 7,766.00
	Less 10%				$ 776.60
					$ 6,989.40
	Towing fee				$ 60.00
	To putty & spray paint				$ 800.00
	To check front wiring & focus head lamp				$ 30.00
	Labour charges.				$ 500.00
TG-VL/-	**Total**				**$ 8,379.40**