CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO **SHC7623X** **DATE 06.04.2023**

MAKE **REG.14.11.2019**

MODEL **: HYUNDAI IONIQ G2** **CHIANG/.** ALLIANZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET LH			? $41.40
1	FRONT BUMPER			de — $481.10
1	FRONR BUMPER GRILLE LH			× $186.50
1	FRONT BUMPER CENTRE MOULDING			× $368.50
1	FRONT HEAD LAMP LH			wt — $2,110.30
1	FRONT DAY RUNNING LIGHT LH			× $642.00
1	FRONT WHEEL RIM COVER LH			wt — $346.40
1	FRONT FENDER LH			bt ? $588.80
1	FRONT FENDER SHIELD LH			$164.70
1	FRONT FENDER EMBLEM			wa $26.60
				$4,956.30
	20.00%			$991.26
	DISCOUNTED TOTAL			**$3,965.04**
	Labour Charge			
	Panel Beating			575 $1,050.00
	Spray Paint			750 $800.00
	Remove/Refix Upholsetry			× $90.00
	Tuff Coating			30 $90.00
	TOWING FEE		towing receipt.	? $60.00
	Check lighting			30 $60.00
	TOTAL LABOUR			**$2,150.00**
	ESTIMATE TOTAL			**$6,115.04**

Tanjin 97445949
WD' 4/4/23 @ 5pm
c/s Resurvey after repair
tanjin c/Khantolan
2-3days

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.