(08/13 /13) wef

ASS_ REC. BY:

REF: CS3/SMR2300384/Ruy3

4192

ASSIGNMENT

COE - 2032/7

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBG 5089B

at Workshop m/s HUA CHIN

of BUKIT BATOK ST 23

Insured: SMR

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 13K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBG 5089B Yr Regn: 2012 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: YAMAHA JUPITER MX (CHC) c.c 134

Colour RED A/C: Insured / Std / NI / NA

Sp.Reading 98047 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MH3506G02GK385113

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/90-17

R: 90/90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TIMSUN

Front		Rear	
R/Bal.	4 mm	R/Bal.	4 mm
L/Bal.	mm	L/Bal.	mm

D.O.A. 31/03/23 D.O.I. 14/04/23

Survey held at HUA CHIN

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	REPAIR LIMIT - 3.5K
	ESTIMATE RANGE OF REPAIR (NO. OF DAYS - (2K - 3K) / 3 days

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

Report Format :

Lump Sum / I.B.I: ($

Survey Fee:

Transportation: S + RS SI

Photos

Others