LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:	CS/TMI23004412/SVY3Q2
Date:	31/05/2023

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MAA00174
Claimant Vehicle No :	SHA4618S	**Insured Vehicle No :**	SMZ2591G
Date of Loss:	28/04/2023	Nature of Claim:	TP Claim No: M2302732

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SHA4618S**		
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Engine No:	D4FDGU659994
Reg. Date:	29/12/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMHU097709
Colour:	Blue	Odometer:	728164 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,120.72	682.40	438.32	39.11
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	650.00	560.00	90.00	13.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**1,781.72**	**1,253.40**	**528.32**	**29.65**
Approved Total (Overridden) (S$)		**1,000.00**		
(S$)	1,781.72	1,000.00	781.72	43.87
+ GST 8.00/8.00% (S$)	142.54	80.00	62.54	43.88
Nett Amount (S$)	**1,924.26**	**1,080.00**	**844.26**	**43.87**

INSPECTION

Date of Assignment:	02/05/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	02/05/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster:	S Mohamed Irfan Bin Mohamed Iqubal	**Manager:**	VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG		Version: 1.0 (Last Synchronised: 30 May 2023)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA4618S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		***REAR BUMPER ASSY**	Deformed	553.00 FL	*553.00 FL
2	10		***REAR BUMPER CLIPS**	Necessary	22.00 FL	*22.00 FL
3	1		***REAR BUMPER BEAM**	Not Necessary	428.40 FL	*- FL
4	1		***REAR BUMPER SPONGE**	Not Necessary	119.50 FL	*- FL
5	1		***REAR BUMPER UNDER COVER**	Scratched	228.00 FL	*228.00 FL
6	1		***REAR BUMPER MAT**	Necessary	50.00 FL	*50.00 FL

F=Franchise part. L=ListItemDisc.

	Repairer's	Amount
Sub Total (S$)	**1,400.90**	**853.00**
- List Item Discount on L Items 20.00/20.00% (S$)	280.18	170.60
Total Parts (S$)	**1,120.72**	**682.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	**OD/TP Case (Insurer)**	11.00	11.00
		Sub Total (S$)	**11.00**	**11.00**

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	**PANEL BEATING**	New	300.00	280.00
2	**SPRAYPAINT**	New	300.00	250.00
3	**REMOVE / REFI REVERSE SENSOR**	New	50.00	30.00
	Gross Labour Cost (S$)		**650.00**	**560.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >