LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

HSBC LIFE (SINGAPORE) PTE LTD

10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983

ATTN: WINNIE HO

Ref: CS3/HSB23004429/Rwp3e2

Date: 12/05/2023

Code: HSB

1. Policy Particulars :- (THIRD PARTY CLAIM)

	Insured Veh.	SJS 2163G	**Veh. Inspected**	FBS 3904Z
	Policy No.	GA465889	**Coverage ($)**	0.00
	Claim No.	S3M04LY0	**Excess ($)**	0.00
	Assign From	WINNIE HO	**Assign Date**	02/05/2023

2. Vehicle Particulars & Condition

	Make & Model	K.T.M. 390 DUKE	**c.c**	373
	Engine No.	HIDDEN	**Year of Reg.**	2017
	Chassis No.	VBKJPJ405HC212014	**Colour**	MULTI COLOUR
	Odometer	-	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	SPORTS RIM
	General	FAIR		

3. Conditions of Tyres

		Size	**Make**	**Balance**
	R/H Front Tyre	110/70Z R17	MICHELIN	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	150/70Z R17	MICHELIN	4 mm
	L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.



5. General Information

	Accident Date	03/03/2023	**Inspect Date / Time**	03/05/2023 (05:16 PM)
	Survey held at	BIKERS AVENUE PTE LTD NO 1 BUKIT BATOK CRESCENT #02-58 WCEGA PLAZA SINGAPORE 658064		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $4,000-$5,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**

Report Ref No. CS3/HSB23004429/Rwp3e2

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.