Surveyor:

REF: CS3/FCI22001816/Tqp3-1

Special Instruction: C 0381

ASSIGNMENT (Office)

From (Person): HARMINDER KAUR of FCI2 Date/Time:

Estimated Cost: Bill to:

TMA: $86880, 14 DAYS
LORRY: L/SUM: 39,500 / REPAIR; 18 DAYS

Third Parties:

Claimant:

Surveyor: CARLINK CONSULTANCY

Workshop: TAN HUP SENG AUTO

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: YP 5047C Insured: SMB 5063X

at Workshop m/s TAN HUP SENG AUTO Tel:

of BLK 19 SIN MING IND. ESTATE #01-09 SINGAPORE 575677

Policy No: Claim No: D22000550MFBP

Sum Insured: Excess:

Make of Veh: D.O.A. 21/02/2022

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig , days (Red $ / %; Original days)

Date/Time: Submit Final Fig , days (Red $ / %; Original days)

Date/Time	Action/Instruction
	14/06/23 SUBMIT TMA : $76630, 10 days. (Red $10050, 12%); SUBMIT LORRY : LS $25050, 16 days (Red $14450, 58%)

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

$580 | 14/6

Para(3) : Nett Value

116x15 = 1740

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:	Date:
Basic & Add	1740+170
Transport	50
Photos	108
Others	
Total	2068

1) Date/Time 14/06/23 File Pass to Typist 2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to