Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883
UEN No: 53291793J liusbro@ymail.com
Tel: 67411730

FINAL BILL

Name: Allianz Insurance Company of Singapore Pte Ltd
Addres Motor Claims Department
79 Robinson Road #09-01
Singapore 068897

Ref Date: 09/07/2023
Ref No: YM7735C230428
Vehicle No: YM7735C
Model / Make: Nissan
Capacity: 7684 cc PKC37BNHNP

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Front	Panel	$ 2,645.20	1	$ 2,645.20		$ -
2		Wiper Panel	$ 668.30	1	$ 668.30		$ -
3		Wiper Garnish "Nissan Diesel" Sticker	$ 60.80	1	$ 60.80		$ -
4		Bumper	$ 1,360.20	1	$ 1,360.20		$ -
5		Corner Panel Garnish Rh	$ 522.30	1	$ 522.30		$ -
6		Side Lamp Rh	$ 285.00	1	$ 285.00		$ -
21		To check all wiring & electrical component for proper function			$ 30.00		$ -
24		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs			$ 800.00		$ -
25		To putty & spray painting & including touch up paint on accident affectecd areas			$ 800.00		$ -
26		To apply Rust Proofing , reseal tuff-coating treatment on accident area			$ 40.00		$ -

Total Parts & Labour of estimate for damaged vehicle	$ 7,211.80
Total amount in Lumpsum Basis for repaired vehicle	$ 3,000.00

SDL Three Thousand Only

Liu's Bro Auto Engrg Wks