MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z
Address: 60 JALAN LAM HUAT,CARROS CENTRE #05-68 S737986
HP: 98888885

Estimation

Date:	15/5/2023
Vehicle:	SMY3842G
Make / Model:	TOYOTA PRIUS
INSURANCE	TM

No.	Description	Unit	Unit Price	Amount	
1	REAR BUMPER	1	$ 658.00	$ 658.00	✓
2	REAR BUMPER SIDE RETAINER	2	$ 112.00	$ 224.00	✓
3	REAR BUMPER REINFORCEMENT	1	$ 350.50	$ 350.50	X
4	REAR BUMPER LIP	1	$ 728.90	$ 728.90	✓
5	REAR BUMPER REFLECTOR LH	1	$ 68.00	$ 68.00	X
				$ 2,029.40	
			Less 20%	$ 405.88	
			Total	$ 1,623.52	
	S/Nett items:				
1	REAR BUMPER CLIPS	1	$ 80.00	$ 80.00	Sola
2	REAR REVERSE SENSOR	1	$ 250.00	$ 250.00	
				$ 330.00	
	Labour to: REAR				
1	TO CHECK REAR ELECTRICAL WIRING	1	$ 150.00	$ 150.00	15L
2	TO REMOVE AND RENEW REVERSE SENSOR	1	$ 150.00	$ 150.00	50d
4	APPLY ANTI RUST ON AFFECTED AREAS	1	$ 100.00	$ 100.00	X
5	SPRAY PAINTING ON AFFECTED AREAS	1	$ 300.00	$ 300.00	22d
6	PANEL BEATING ON AFFECTED AREAS	1	$ 300.00	$ 300.00	20d
				$ 1,000.00	

Parts Replacement Amount	$ 1,953.52
Total Amount for Labour	$ 1,000.00
Total Amount	$ 2,953.52

NOT Authorised
L/Pay B
Resurvey After Paint
2days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Sig