DEPT: Swy REF: CS3/INC23001755/Swy3-1

ASS. REC. BY:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: Inc

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 70 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SME440BP Yr Regn: 21/Oct/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: honda hrv cc 1496

Colour: Black A/C: Insured / Std / Nil / NA

Sp.Reading: 305723 T/Radio: Insured / Std / Nil / NA

Eng/No: -

C/No: JHMRU1810GX200842

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim, or

Tyre Size: F: 215/55R17
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm

D.O.A. 28/1/23 D.O.I. 16/2/23 130

Survey held at: RS garage.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Balance: 44.7m
	est Repair cost / $3500 - $4500 yearly: 13k
	mv: 51k
	NV: 21k
24/05/2023	Submit L/S $2,800.00 @ 4 days (Red $3,400.00/55%)
	high mileage -5k
	DIS - 16/2/23 230pm

Date/Time, File Pass to? 24/05/2023
1) typist

[ ] : Prell. Report
[✓] : Final Report

Date/Time, File Return to?
2)

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee: [ ] : Site Insp ($) [ ] : Interview ($) [ ] : Tech. Invs ($) [ ] : Weekend ($)

Survey Fee:
Transportation:
S + RS SI
Photos
Others
TOTAL

Report Format: Paper Survey

Lump Sum / I.B.I: ($ $2,800)

Scanned with CamScanner