(08/11 /13) wef

ASS. REC. BY: / Taufikh

REF: INC NS/INC23006074/Tnp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. MT/1227716-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD6813R. Yr Regn: 2016, April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Mercedes Benz E220 c.c 2143.

Colour white A/C: Insured / Std / NI / NA

Sp.Reading 76259 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2120012B345675.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 225/55R16

R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Hifly

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	15/6/23

Survey held at Comfort Lorong 5

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or o/s rear.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Taufikh confirmed lump sum $4000 and 4 days (red, $2076, 34%)

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Survey Fee:

Transportation: ___S+RS, ___SI

Photos

Others

Report Format : _____

Lump Sum / I.B.I: ($ _____)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO **SHD6813R** DATE **15.06.2023**

MAKE **REG. 08.04.2016** **CHIANG /INCOME**

MODEL **MERC E6**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			$1,510.00
1	REAR BUMPER RETAINER			$115.00
1	REAR DOOR PANEL LH RH			$2,870.00
1	REAR WHEEL RIM RH			$1,250.00
	SUB TOTAL			**$4,495.00**
	LESS 20%			$899.00
				$3,596.00
1	DOOR COMFORT/MAXI STICKER			$80.00
				$80.00
	Labour Charge			
	Panel Beating		600	$900.00
	Spray Painting Charge		1000	$1,200.00
	Remove/Refix Upholstery rear			$120.00
	Remove/Refix Door Parts		60	$180.00
	TOTAL LABOUR			**$2,400.00**
	ESTIMATE TOTAL			**$6,076.00**

Tanjohn 97495949
insp: 15/6/23 @ 4.30 pm
c/s resurvey after repair
tanjohn @ thanks.com
3 days

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755
Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286

Date/Time: 15.06.2023 13:40 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5900362

JC NO305557764

CUSTOMER

M/S COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

ACCOUNT CARD NO.

REGN NO.: SHD6813R	MILEAGE
MAKE: MERCEDES BENZ	FUEL E.....1/2.....F
MODEL E220CDI(E6)	DATE/TIME IN 15.06.2023 11:50
YR OF MANU. 08.04.2016	TARGET DATE
CHASSIS CODE WDD2120012B315675	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 15.06.2023
NATURE: 3P 15.06.2023

S/NO	LABOR CODE	DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

No.: SHD6813R CHIANG

Service Advisor

Signature/Date

Returned to Service Reception upon collection

Exit Pass

Vehicle No.: SHD6813R

Name of Service Advisor

Date

To be kept by Security Guard