PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0593/2023/EQ
DATE	:	23-Jun-23
WIP	:	26105

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/6/2023

YOUR INSURED VEH NO : GBC 1385 T

Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897
Attn: Motor Claims Dept

OWNER'S NAME	:	MS FARAHDIAN BTE ABDUL AZIZ
ADDRESS	:	261 RIVER VALLEY ROAD #15-20, ASPEN HEIGHTS SINGAPORE 238307
TELEPHONE	:	HP +65 82345167
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	7220104791
VEHICLE NO	:	**SMZ 1083 M**
MODEL CODE	:	AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR	:	12/10/2020
ENGINE NO	:	DEM 025196
CHASSIS NO	:	WAUZZZF50LA022337
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	22-Jun-23
PLACE OF ACCIDENT	:	JUNCTION OF CENTRAL BLVD AND SHEARES AVENUE

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 1083 M

S/N	NATURE OF JOBS			ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N	$	360.00	✓
2	TO RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N	$	300.00	✓
3	TO INSTALL SOLAR FILM FOR AFFECTED GLASS.	S/N	$	400.00	✓
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N	$	1,600.00	✓
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N	$	1,600.00	✓
6	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N	$	400.00	✓
	TOTAL LABOUR CHARGES	:	**$**	**4,660.00**	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 1083 M

S/N	NATURE OF JOBS			ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. TO REMOVE AND REINSTALL LHS SILL PANEL TRIM. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		$	~~7,200.00~~	5600
8	TO RESPRAY REAR BUMPER, LHS REAR DOOR, LHS REAR FENDER, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING.		$	3600 ~~6,500.00~~	4.5 x 800 = 3600
9	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N	$	280.00	✓
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	$	192.00	✓
	TOTAL LABOUR CHARGES	:	**$**	**18,832.00**	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 1083 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1	REAR BUMPER Dehomed	1	$ 2,763.00	✓
2	REAR BUMPER SECURING STRIP - UPPER ?	1	$ 133.00	?
3	REAR BUMPER SECURING STRIP - LOWER ?	1	$ 264.00	?
4	REAR BUMPER SPOILER Cut	1	$ 292.00	✓
5	REAR BUMPER BRACKET - LH New	1	$ 241.00	?
6	REAR BUMPER REFLECTOR - LH INNER / OUTER New	2	$ 102.00	X
7	REAR BUMPER GUIDE SECTION - LH ?	1	$ 52.00	?
8	REAR BUMPER GUIDE SECTION - LH UPPER ?	1	$ 27.00	?
9	REAR BUMPER HOLDING STRAP - LH ?	1	$ 100.00	?
10	REAR PARKING AID SENSOR - LH New	1	$ 272.00	X
11	REAR PARKING AID SEAL RING New	4	$ 11.00	X
12	REAR SIDE PANEL - LH Dented	1	$ 4,315.00	✓
13	REAR QUARTER WINDOW - LH ok	1	$ 844.00	✓
14	WINDOW PRIMER ok	1	$ 24.00	✓
15	ATTACHMENT PARTS New	1	$ 144.00	+
16	ADHESIVE TAPES ok	1	$ 230.00	✓
17	REAR WHEEL HOUSING LINER - LH New	1	$ 322.00	+
18	REAR DOOR - LH Dented	1	$ 4,210.00	✓
19	REAR DOOR OUTER SEAL - LH ok	1	$ 261.00	✓
20	BONDING AGENT ?	1	$ 51.00	?
	SUB TOTAL SPARE PARTS	:	**$ 14,658.00**	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 1083 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21	CLEANING SOLUTION ?	1	$ 80.00 ?	
22	APPLICATOR ?	1	$ 9.00 ?	
23	REAR DOOR ATTACHMENT PARTS New	1	$ 191.00 +	
24	REAR DOOR CATCH - LH ?	1	$ 141.00 ?	
25	REAR ALUMINIUM RIM - LH Lt	1	$ 2,000.00 ✓	(Poiáry ???)
26	REAR ALUMINIUM RIM RUBBER VALVE New	1	$ 4.00 +	
27	REAR VENT TRIM New	1	$ 77.00 +	
28	ACRYLIC SEALANT ?	S/N	$ 180.00 ✓	
29	CAVITY WAX	S/N	$ 140.00 ✓	
30	STONE CHIP New	S/N	$ 180.00 ✓	
31	METAL FILLER POWDER	S/N	$ 280.00 ✓	
32	1/4 GLASS SEALANT	S/N	$ 100.00 ✓	
33	SUNDRIES ?		$ 600.00 ?	
	TOTAL SPARE PARTS	:	**$ 18,640.00**	
	TOTAL LABOUR CHARGES	:	**$ 18,832.00**	
	GRAND TOTAL	:	**$ 37,472.00**	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME	:	Adrian Ling
SURVEYED DATE	:	28/06/23.
AUTHORISED DATE	:	
EXCESS COST	:	
LIABILITY	:	
REMARKS	:	Not Authorised, 14 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

TEK Auto Consultants hence notify the Repairer of the following:
- To resurve [illegible] pre/after spray painting
- To display [illegible] aged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT