LIM TAN MOTOR

ESTIMATE TO REPAIR

VEHICLE NO.	: SMC 1198 L
MAKE	: HYUNDAI
MODEL	: I30
YEAR	: 2018
CHASSIS NO	: TMAH3513VJJ065294

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

DATE	: 08-Jul-23
DATE OF ACCIDENT	: 07-Jul-23
THIRD PARTY REF	SLG 9241 H
THIRD PARTY REF	CHINA TAIPING INSURANCE

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount	
1 pc	Rear bumper				$ Bn 801.60	✓
1 pc	Rear bumper reinforcement				$ 431.60	✓
1 pc	Rear bumper lower lip				$ 226.50	✓
					$ 1,459.70	
	Less 20%				$ 291.94	
					$ 1,167.76	
1 Set	Rear bumper sensor	S/N			$ Sn 200.00	X
1 pc	Rear number plate	S/N			$ Nel 40.00	✓
	To putty & spray paint				$ 300.00	220L
	Labour charge				$ 250.00	200
TG/ZX	TOTAL				$ 1,957.76	

Not authorised
C/Pay ©
Resurvey after Paint
2days

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary claim(s) must be received and is subject to final approval from Insurance Company

Received by Repairer

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64559127 Email: edmund@LTM.sg
Co. Reg No. 199307277D GST Reg No. M2-0019066-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd