

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0458/2024/KS
DATE : 10-Jun-24
WIP : 18705

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/6/2024.

YOUR INSURED VEH NO : SMC 1230 B

AIG Asla Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR. NICKY H GURNANI
ADDRESS : 21 SAMPAN PLACE
#10-03
SINGAPORE 436593
TELEPHONE : HP +65 90298383
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7230082717
VEHICLE NO : SLH 9999 A
MODEL CODE : AUDI Q5 2.0 TFSI QU S-TRONIC
MODEL YEAR : 20/8/2021
ENGINE NO : DGK 006528
CHASSIS NO : WAUZZZF1M2099157
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Jun-24
PLACE OF ACCIDENT : NEAR FORT ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLH 9999 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00 /	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00 300	
3	TO RESPRAY REAR BUMPER UPPER, REAR BUMPER MID AND BOTH REAR WHEEL ARCH TRIMS. 2 1/2 x 2	S/N \$	2,500.00 1500	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00 /	
TOTAL LABOUR CHARGES		:	<u>\$ 4,752.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLH 9999 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER / <i>00</i>	1	\$ 3,067.00 / 3,069.60	
2	REAR BUMPER TRIM <i>LH/RH</i> X <i>nn</i>	2	\$ 286.00	
3	REAR BUMPER BLACK SPOILER / <i>cut</i>	1	\$ 406.00 / 324.40	
4	REAR DIFFUSER / <i>cut</i>	1	\$ 429.00 / 338.00	
5	REAR TRIM <i>LH / RH</i> (<i>LH</i>) / <i>cut</i> (<i>chrome</i>)	1	\$ 614.00 245.20 /	
6	REAR TRIM CENTRE X (<i>chrome</i>) <i>nn</i>	1	\$ 209.00	
7	REAR TAILLIGHT <i>LH / RH</i> <i>OR</i> /	1	\$ 1,750.00 699.60 /	
8	REAR SENSOR X <i>nn</i>	1	\$ 286.00	
9	REAR SENSOR SEAL X <i>nn</i>	4	\$ 11.00	
10	REAR BUMPER REINFORCEMENT BEAM X <i>nn</i>	1	\$ 1,195.00	
11	REAR BUMPER FOAM ? X <i>nn</i>	1	\$ 79.00	
12	REAR BUMPER HOLDING STRAP ? X <i>nn</i>	1	\$ 213.00	
13	REAR WHEEL COVER REAR LH / RH / <i>np</i>	2	\$ 1,389.00 / 1,110.40	
14	SUNDRIES ? X <i>nn</i>	1	\$ 300.00	
TOTAL SPARE PARTS		:	\$ 10,997.00	
TOTAL LABOUR CHARGES		:	\$ 4,752.00	
GRAND TOTAL		:	\$ 15,749.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Steve (LKK)
: 12/6/24, 10.30am
:
:
:
:

W R
P/P
by P/L sy
3 dgt

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT