



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24060010/Aqp3
75 BRAS BASAH ROAD	Date:	10/09/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLD 5840X	Veh. Inspected	SLP 4967H
Policy No.	-	Coverage	0
Claim No.	MT/1280870-001	Excess	\$0.00
Assign From	SITI RAUDHAH	Assign Date	10/06/2024

2. Vehicle Details

Make & Model	MAZDA 3	C.C	1496
Engine No.	P520451031	Year of Reg.	07/06/2017
Chassis No.	JM6BN22A8H0158363	Colour	BLACK
Odometer	291420 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60 R16	DUNLOP	6
L/H Front Tyre	205/60 R16	DUNLOP	6
R/H Rear Tyre	205/60 R16	DUNLOP	6
L/H Rear Tyre	205/60 R16	DUNLOP	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/06/2024	Inspection Date	10/06/2024 (14:18)
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days