

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9, Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

not Authorized
 m
 mers
 16/7/24
 4/5 \$3600
 3 days

M/S : India International Insurance Pte Ltd

64 Cecil Street

#04/ #05/ #06-02

IOB Building Singapore 049711

TEL: 6347 6100

FAX: 6224 4174 / 6225

ATTN: Motor Claim Department

Estimate No: ES1602114

Date: 27 Mar 2024

Policy No: DMCG23006911

Veh Reg No: XD9022Y

Make/Model: MITSUBISHI FUSO
 FV51SJD2DEA

Chassis No: FV51SJA10037

Engine No: OM457LA457972C028508

Reg. Date: 06/06/2014

Your Ref No: SOON HUA BEE PL

Claim Type: Third Party

Accident Date: 27/03/2024

TP Veh Reg No: SJW2823P

Estimate Repair Cost to Vehicle No :XD9022Y

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 Front Bumper <i>DS/3mt</i>	2,259.31	1 PC	2,259.31	✓
2 Front Bumper Cover -LH <i>R</i>	305.89	1 PC	305.89	X
3 Front Bumper Side -LH <i>7m</i>	140.29	1 PC	140.29	✓
4 Front Bumper Step Garnish <i>C/A</i>	217.26	1 PC	217.26	✓
5 Front Bumper Lower Stay <i>11</i>	169.07	2 PC	338.14	X
6 Front Bumper Bracket <i>11</i>	37.30	1 PC	37.30	X
7 Front Bumper Side Air Dust -LH <i>11</i>	96.70	1 PC	96.70	X
8 Front Top Bumper <i>R</i>	273.12	1 PC	273.12	X
9 Front Top Bumper Reinforcement <i>11</i>	884.79	1 PC	884.79	X
10 Front Top Bumper -LH <i>11</i>	193.04	1 PC	193.04	X
11 Front Top Bumper Reinforcement -LH <i>11</i>	226.06	1 PC	226.06	X
12 Front Headlamp Assy -LH <i>11</i>	1,286.45	1 PC	1,286.45	X
13 Front Headlamp Rim -LH <i>C/A</i>	181.18	1 PC	181.18	✓
14 Front Headlamp Aluminium Bracket -LH <i>11</i>	947.63	1 PC	947.63	X
15 Front Fog Lamp Assy -LH <i>11</i>	293.25	1 PC	293.25	X
16 Front Fog Lamp Rim -LH <i>C/A</i>	186.05	1 PC	186.05	✓
17 Front Door Lamp -LH <i>11</i>	195.03	1 PC	195.03	X
18 Stand Panel -LH <i>C/A</i>	744.59	1 PC	744.59	✓
19 Stand Panel Alloy Mat Centre -LH <i>11</i>	289.84	1 PC	289.84	X
20 Stand Panel Side Bracket -LH <i>SU</i>	254.70	1 PC	254.70	X
21 Step Panel -LH <i>R</i>	324.55	1 PC	324.55	X
22 Step Panel Lower -LH <i>C/A</i>	270.56	1 PC	270.56	✓
23 Step Panel Under Cover -LH <i>7m</i>	229.87	1 PC	229.87	✓
24 Step Panel Reflector -LH <i>SU</i>	123.45	1 PC	123.45	X
25 Step Alloy Mat -LH <i>C/A</i>	326.00	1 PC	326.00	✓
26 Step Holder Front -LH <i>11</i>	875.91	1 PC	875.91	X
27 Step Holder Rear -LH <i>11</i>	629.25	1 PC	629.25	X
			12,130.21	
		Less 25%	3,032.55	9,097.69
Labour				
28 To remove & refit headlamp cable ,system & check wiring & refocus all light .	230.00	1 -	230.00	20
29 Labour charge to cut & weld & dismantle & remove & refit all above parts .	1,800.00	1 -	1,800.00	600
30 To rust proofing on affected area .	850.00	1 -	850.00	X
31 To spray & painting all accident affected area .	1,500.00	1 -	1,500.00	SU

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9, Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

M/S : India International Insurance Pte Ltd

64 Cecil Street

#04/ #05/ #06-02

IOB Building Singapore 049711

TEL: 6347 6100

FAX: 6224 4174 / 6225

ATTN: Motor Claim Department

Your Ref No: SOON HUA BEE PL

Claim Type: Third Party

Accident Date: 27/03/2024

TP Veh Reg No: SJW2823P

Estimate No: ES1602114

Date: 27 Mar 2024

Policy No: DMCG23006911

Veh Reg No: XD9022Y

Make/Model: MITSUBISHI FUSO
FV51SJD2DEA

Chassis No: FV51SJA10037

Engine No: OM457LA457972C028508

Reg. Date: 06/06/2014

Estimate Repair Cost to Vehicle No :XD9022Y

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
			4,380.00	4,380.00
Total				S\$ 13,477.69
Add GST @ 9%				1,212.99
Total Amount Payable				S\$ 14,690.68

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND SIX HUNDRED NINETY AND CENTS SIXTY EIGHT ONLY

For HUP LIAN HUAT ENGINEERING
WORKS

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-4555.11
 252
 3416.33
 1120
 4536.33
 202
 3629