



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBD 4523L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT HEADLAMP ASSY	CRACKED	\$520.00	\$520.00
1	FRONT CORNER PANEL	TO REPAIR SEE LABOUR	\$250.00	\$0.00
1	FRONT BUMPER ASSY	TO REPAIR SEE LABOUR	\$750.00	\$0.00
2	FRONT BUMPER BRACKET	NOT NECESSARY	\$100.00	\$0.00
1	FRONT R/H DOOR ASSY	DAMAGED	\$1,750.00	\$1,750.00
1	FRONT R/H DOOR PILLAR (NPA)	TO REPAIR SEE LABOUR	\$789.10	\$0.00
1	FRONT R/H DOOR WEATHERSTRIP	NOT NECESSARY	\$140.00	\$0.00
1	FRONT DOOR INNER STEP GARNISH	NOT NECESSARY	\$110.00	\$0.00
	LESS 25.00% DISCOUNT		(\$1,102.28)	(\$567.50)
			\$3,306.82	\$1,702.50

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR COMPANY STICKER (SN)	NECESSARY	\$80.00	\$50.00
			\$80.00	\$50.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO TRANSFER FRONT DOOR COMPONENTS TO NEW DOORS	NOT NECESSARY	\$180.00	\$50.00
	TO REMOVE / REINSTALL SEAT, UPHOLSTERY, TRIMS & GARNISH TO ASSIST REPAIRS		\$150.00	\$0.00
	LABOUR CHARGES TO REPAIR AND PANEL BEAT FRT FENDER INNER PANELS, CHASSIS, RE-ALIGN FRT PILLARS, CUTTING/WELDING AND REPLACING THE ABOVE MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF FRONT CORNER PANEL, FRONT BUMPER ASSY AND FRONT R/H DOOR PILLAR		\$1,400.00	\$400.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT THE AFFECTED AREAS		\$1,000.00	\$500.00
	TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANELS		\$150.00	\$30.00
			\$2,880.00	\$980.00

GRAND TOTAL			\$6,266.82	\$2,732.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$2,150.00
Report Ref No: CS1/SPF24080174/Enp3e2				

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,150-\$2,400



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.