

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: ACS/105/009/2024/038 (CF) Date: 21st Aug 2024

Our Ref: CS1/SPF24080174/Enp3e2

M/s Automotive Engrg. & Mgt. Division (TP)

Accident Claims Section
(Spore Police Force)
Police Logistics Base (PLB)
1 Hemmant Road
Singapore 438675
(The Motor Claims Department)

Attn: Lai Peng Chong

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBD 4523L INSURED VEHICLE: QX 1783P

ACCIDENT DATE: 20/04/2024

We thank you for your instruction on 08/08/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBD 4523L from M/s Automax Survey.
- b) Final Repair Bill of GBD 4523L from M/s Eng Soon Painting Services.
- c) Singapore Accident Statement and Police Report of Vehicles GBD 4523L.
- d) Colour damaged vehicle photographs of GBD 4523L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : GBD 4523L
Make & Model : Toyota Dyna 150
Chassis Number : JTFAT35Y30K203777

Year of Registration : 2015 Engine Capacity : 2986 cc

- 2. We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.