

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S: CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2400328
Date: 12 Aug 2024

Veh Reg No: SNR9109B
Make/Model: MERCEDES BEN E220D
AUTO

Chasis No: WDD2130042A029504

Reg. Date: 28/09/2016

Your Ref No: YP9619B

Claim Type: Third Party

Accident Date: 10/08/2024

TP Veh Reg No: YP9619B

Estimate Repair Cost to Vehicle No :SNR9109B

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC FRT DOOR LH <i>Dented</i>	3,316.00	✓
2	1 PC FRT DOOR RUBBER LH <i>new</i>	389.00	✓
3	1 PC FRT DOOR OUTER HANDLE LH	277.00	X
4	1 PC FRT DOOR HANDLE INNER BRACKET LH <i>new</i>	282.00	X
5	1 PC FRT DOOR INNER LOCK LH <i>Damaged</i>	766.00	895
6	1 PC FRT DOOR GLASS REGULATOR LH <i>new</i>	1,218.00	345
7	1 PC FRT DOOR GLASS REGULATOR MOTOR LH <i>new</i>	907.00	X
8	1 PC FRT DOOR TRIM LH <i>cracked</i>	2,413.00	350
9	1 PC FRT DOOR OUTER MOULDING LH	271.00	X
10	1 PC FRT DOOR CHANNEL RUBBER LH <i>new</i>	393.00	X
11	1 PC FRT DOOR LOWER RUBBER LH	193.10	X
12	1 PC FRT DOOR FRAME CHROME MOULDING LH <i>new</i>	399.00	X
13	1 PC FRT DOOR REGULATOR CONTROL RELAY <i>new</i>	587.00	X
14	1 PC FRT DOOR SIDE MIRROR ASSY LH <i>cracked</i>	1,710.00	1340
15	1 PC FRT DOOR SIDE MIRROR OUTER COVER LH <i>cracked</i>	287.00	140
16	1 PC FRT DOOR SIDE MIRROR GLASS LH <i>cut</i>	398.00	✓
17	1 PC FRT SIDE MIRROR SIGNAL LIGHT LH <i>cut</i>	261.00	✓
18	1 PC FRT DOOR SIDE MIRROR LOWER COVER LH <i>new</i>	362.00	X
19	1 PC REAR DOOR LH <i>Dented</i>	3,569.00	✓
20	1 PC REAR DOOR SURROUND RUBBER LH <i>new</i>	388.00	✓
21	1 PC REAR DOOR TOP HINGE LH <i>new</i>	106.00	X
22	1 PC REAR DOOR BOTTOM HINGE LH <i>new</i>	127.00	X
23	1 PC REAR DOOR OUTER MOULDING LH <i>new</i>	289.00	X
24	1 PC REAR DOOR OUTER HANDLE LH <i>Missing</i>	299.00	✓
25	1 PC REAR DOOR OUTER HANDLE INNER BRACKET LH <i>Missing</i>	261.00	✓
26	1 PC REAR DOOR INNER LOCK LH <i>new</i>	797.00	610
27	1 PC REAR DOOR RUBBER LH <i>new</i>	364.00	✓
28	1 PC REAR DOOR OUTER HANDLE SMALL COVER LH <i>Missing</i>	76.00	✓
29	1 PC REAR DOOR TRIM LH <i>cracked</i>	2,428.00	395

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2400328

Date: 12 Aug 2024

Veh Reg No: SNR9109B
Make/Model: MERCEDES BEN E220D
AUTO

Chasis No: WDD2130042A029504

Reg. Date: 28/09/2016

Your Ref No: YP9619B

Claim Type: Third Party

Accident Date: 10/08/2024

TP Veh Reg No: YP9619B

Estimate Repair Cost to Vehicle No :SNR9109B

Quantity	Description	List Price	Amount
		SS	SS
30	1 PC REAR DOOR GLASS REGULATOR LH <i>and</i>	1,224.00	480.
31	1 PC REAR DOOR GLASS REGULATOR MOTOR LH <i>and</i>	893.00	580.
32	1 PC REAR DOOR FRAME CHROME MOULDING LH <i>3 new</i>	382.00	X
33	1 PC REAR DOOR ANGLE GLASS BRAZE PANEL	178.00	X
34	1 PC REAR DOOR GLASS CHANNEL RUBBER <i>ut</i>	380.00	/
35	1 PC REAR DOOR GLASS REGULATOR RELAY CONTROL LH <i>new</i>	632.00	X
36	1 PC REAR DOOR LOWER RUBBER LH <i>ut</i>	173.00	/
37	1 PC REAR DOOR SIDE RUBBER LH <i>ut</i>	194.00	/
38	1 PC REAR FENDER LH <i>Dented</i>	3,670.00	3310
39	1 PC REAR WINDSCREEN RUBBER <i>new</i>	279.00	/
		31,139.10	
		Less 10%	3,113.91
			28,025.19
	Special Net		
40	1 SET FRT DOOR TRIM CLIP LH <i>new</i>	40.00	30
41	1 SET REAR DOOR TRIM CLIPS LH <i>120</i>	40.00	30
42	1 PC REAR WINDSCREEN SEAL <i>new</i>	60.00	30
43	1 PC REAR WINDSCREEN SEALANT <i>new</i>	60.00	30
		200.00	200.00
	Labour		
44	1 TO CHECK WIRING	200.00	30
45	1 TO REMOVE AND REFIT DOOR GLASS LH	150.00	40
46	1 TO TRANSFER FRONT DOOR WIRING & MECHANICAL ASSY PLUS DOOR TRIM	400.00	40
47	1 TO REMOVE AND REFIX REAR DOOR GLASS LH	100.00	40
48	1 TO TRANSFER REAR DOOR WIRING & MECHANICAL ASSY PLUS DOOR TRIM	400.00	40
49	1 TO REMOVE AND REFIT CUSHION & REAR INNER TIRM	480.00	80
50	1 TO REMOVE AND REFIT REAR WINDSCREEN	200.00	120
51	1 TO SPRAY PAINTING	1,500.00	850

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2400328
Date: 12 Aug 2024

Veh Reg No: SNR9109B
Make/Model: MERCEDES BEN E220D
AUTO
Chasis No: WDD2130042A029504
Reg. Date: 28/09/2016
Your Ref No: YP9619B

Claim Type: Third Party
Accident Date: 10/08/2024
TP Veh Reg No: YP9619B

Estimate Repair Cost to Vehicle No :SNR9109B

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
52	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,000.00 <i>1100</i>	
53	1 TO PROGRAM AND SETTING <i>2490</i>	500.00 <i>150</i>	
		5,930.00	5,930.00
		Total	SS 34,155.19
		Add GST @ 9%	3,073.97
		Total Amount Payable	SS 37,229.16

TOTAL: SINGAPORE DOLLAR THIRTY SEVEN THOUSAND TWO HUNDRED TWENTY NINE AND CENTS SIXTEEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

for
AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
L/S 12/08/24
28 days
total 21511.80
L/S: 17.2K
17.2K