

FIX AUTO PTE LTD

5 SOON LEE STREET # 01-61 (PIONEER POINT) SINGAPORE 627607

PANG ENG HIANG
5 Soon Lee Street
01-61 (Pioneer Point)
Singapore 627607

13th August 2024

Accident date: 07th AUGUST 2024

Estimated repair cost for vehicle no: SKT2045Y VOLVO S60 (COE TIL MAY 2025)

S/n	Qty	Items	U/price	Amount
1	1	boot lid 02 logo X NN		\$60.00 X
2	1	Rear boot lid Volvo logo X NN		\$100.00 X
3	1	Rear boot lid S60 logo X NN		\$85.00 X
4	1	Rear Bumper de/		\$1,688.00 1440
5	2	Rear Bumper Side Bracket X NN	\$188.00	\$376.00 X
6	2	Rear Bumper side retractor X NN	\$225.00	\$450.00 X
7	1	Rear Bumper Reverse Sensor-set NN		\$800.00 S/N-200
8	1	Rear Bumper towing cover X NN		\$155.00 X
9	1	Rear bumper clips-set NN		\$65.00 50 S/N
10	1	Rear bumper lower lip de/		\$588.00 486.40
11	1	Rear Bumper reinforcement X NN		\$1,126.00 X
12	1	Rear Bumper inner sponge X NN		\$322.00 X
13	1	Rear end panel to repair photo X R		\$1,250.00 X 2736.40
14	1	Rear End Panel Top Garnish X NN		\$363.00 X 10%
15	1	Rear spare tire panel top cover X NN		\$655.00 X
16	1	Rear Exhaust aluminium cover X cut		\$250.00 165 2462.76
17	1	Rear Bumper Center Bumper de/		\$850.00 645
			Subtotal :-	\$8,333.00 S/N-250

Labour charges

To remove & re-fix cushion

Hp 900/10068

\$120.00 X

To remove & re-fix reverse sensor

3 days

\$120.00 60

To Check Wiring System

4/5

\$60.00 X 560

Tuff Kote

14/08/24

\$120.00 X

Panel beating

Repair after repair

\$600.00 400 200

Spray painting

\$600.00 300

2462.76

Subtotal :-

\$1,620.00

250.00

Total:-

\$9,953.00

560.00

3272.76

20%
2618.20

4/5 - \$2,600 / 3 days