

**FIX AUTO PTE LTD**  
 5 SOON LEE STREET # 01-61 ( PIONEER POINT ) SINGAPORE 627607

PANG ENG HIANG  
 5 Soon Lee Street  
 # 01-61 ( Pioneer Point )  
 Singapore 627607

13<sup>rd</sup> August 2024

Accident date: 07<sup>th</sup> AUGUST 2024

Estimated repair cost for vehicle no: SKT2045Y VOLVO S60 ( COE TIL MAY 2025 )

S/n	Qty	Items	U/price	Amount
1	1	boot lid 02 logo	\$60.00	✓
2	1	Rear boot lid Volvo logo	\$100.00	✓
3	1	Rear boot lid S60 logo	\$85.00	✓
4	1	Rear Bumper	\$1,688.00	✓ 1440
5	2	Rear Bumper Side Bracket	\$188.00	\$376.00
6	2	Rear Bumper side retrainer	\$225.00	\$450.00
7	1	Rear Bumper Reverse Sensor-set	\$800.00	✓ S/N-200
8	1	Rear Bumper towing cover	\$155.00	✓
9	1	Rear bumper clips-set	\$65.00	✓ S/N
10	1	Rear bumper lower lip	\$588.00	✓ 486.40
11	1	Rear Bumper reinforcement	\$1,126.00	✓
12	1	Rear Bumper inner sponge	\$322.00	✓
13	1	Rear end panel	\$1,250.00	✓ 2736.40
14	1	Rear End Panel Top Garnish	\$363.00	✓ 10%
15	1	Rear spare tire panel top cover	\$655.00	✓
16	1	Rear Exhaust aluminium cover	\$258.00	✓ 165 2462.76
17	1	Rear Bumper center bumper	\$850.00	✓ 645
Subtotal :-				<u>\$8,333.00</u>
S/N-250				

Labour charges

To remove & re-fix cushion

Posit  
Hg 90010068

\$120.00

✓

To remove & re-fix reverse sensor

3 days

\$120.00

60

560

To Check Wiring System

1/3

\$60.00

✓

Tuff Kote

14/08/24

\$120.00

✓

Panel beating

\$600.00

400

200

Spray painting

\$600.00

300

\$600.00

2462.76

Subtotal :-

\$1,620.00

250.00

Total:-

\$9,953.00

560.00

4/3 - \$2,600 / 3 days

3272.76

209

2618.20