

FIX AUTO PTE LTD

5 SOON LEE STREET # 01-61 (PIONEER POINT) SINGAPORE 627607

PANG ENG HIANG
5 Soon Lee Street
01-61 (Pioneer Point)
Singapore 627607

13rd August 2024

Accident date: 07th AUGUST 2024

Estimated repair cost for vehicle no: SKT2045Y VOLVO S60 (COE TIL MAY 2025)

S/n	Qty	Items	U/price	Amount
1	1	boot lid 02 logo X		\$60.00 X
2	1	Rear boot lid Volvo logo X		\$100.00 X
3	1	Rear boot lid S60 logo X		\$85.00 X
4	1	Rear Bumper de/		\$1,688.00 1440
5	2	Rear Bumper Side Bracket ? X	\$188.00	\$376.00 X
6	2	Rear Bumper side retractor X	\$225.00	\$450.00 X
7	1	Rear Bumper Reverse Sensor-set n/ no extra photo w/ throwaway		\$800.00 S/N-200
8	1	Rear Bumper towing cover X		\$155.00 X
9	1	Rear bumper clips-set n/		\$65.00 50 S/N
10	1	Rear bumper lower lip de/		\$588.00 486.40
11	1	Rear Bumper reinforcement ? X		\$1,126.00 X
12	1	Rear Bumper inner sponge ? X		\$322.00 X
13	1	Rear end panel photo photo? X		\$1,250.00 X 2736.40
14	1	Rear End Panel Top Garnish X		\$363.00 X 10%
15	1	Rear spare tire panel top cover X		\$655.00 X 2462.76
16	1	Rear Exhaust aluminium cover * c/nt		\$258.00 165
17	1	Rear Bumper Center Bumper de/		\$850.00 645
Subtotal :-				\$8,333.00 S/N-250

Labour charges

To remove & re-fix cushion

Hp 90010068

\$120.00 X

To remove & re-fix reverse sensor

3 days

\$120.00 60

To Check Wiring System

4/5

\$60.00 X 560

Tuff Kote

14/08/24

\$120.00 X

Panel beating

Resin after repair

\$600.00 400 200

Spray painting

\$600.00 300

2462.76

Subtotal :-

\$1,620.00

250.00

Total :-

\$9,953.00

560.00

3272.76

20%

2618.20

4/5 - \$2,600 / 3 days