

Not Authorized
 4 days 13/8/24 2/5 & 2800
 who photo Aksepi

YEW HOK AUTO SERVICES

522 Bedok North Ave 1, #11-310, Singapore 460522

H/P: 8285 7623

Email: yhlee@outlook.sg

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Damage to undamaged parts "Without Prejudice" basis
- Minor damage to paintwork is allowed
- Supplementary item(s) must be resurveyed and
- Subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle number: GBB8320P

Vehicle Made & Model: MITSUBISHI L200

Qty	^{NOT} List Items	Amount \$
1	Tailgate 20/Buf	1,350.00 ✓
1	Tailgate lock - LH n	185.00 X
1	Tailgate stopper - LH cut	22.00 ✓
1	Tailgate seal 1/1	18.00 ✓
2	Tailgate hinges @ 85 n	170.00 X
1	Tailgate checker - LH n	115.00 X
1	Tailgate lower member n	486.00 X
1	Taillamp - LH 5/20	293.00 ✓
1	Taillamp panel - LH 20/Buf	155.00 ✓
1	Rear fender - LH n	1,850.00 X
1	Rear fender reflector 4/5/20	82.00 ✓
Sub-total		4,726.00
Less 10%		472.60
Total List		4,253.40

Special Nett Items

1	Tailgate aluminium board n	450.00 X
1	Rear sticket " 70 KM/H" n	10.00 ✓
1 set	Rear reverse sensor su	280.00 X
Total Special Nett		740.00

Labour charges

To respray undercoating	100.00 40
To check rear wiring	50.00 20
To remove, refix rear reverse sensor	80.00 30
To respray painting and etc	900.00 880
Panel beating, cut, weld remove & replacing above parts	900.00 800
Total Labour	2,030.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 7,023.40

2-1920
 102
 1728.00
 10
 1770
 3508
 2800