



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24080179/Uvh3
75 BRAS BASAH ROAD	Date:	21/08/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNR 3870A	Veh. Inspected	GBB 8320P
Policy No.	-	Coverage	0
Claim No.	MT/1289888-002	Excess	\$0.00
Assign From	JULIE	Assign Date	12/08/2024

2. Vehicle Details

Make & Model	mitsubishi L200 DOUBLE CABIN	C.C	2477
Engine No.	4D56UCBP8351	Year of Reg.	20/05/2010
Chassis No.	MMCJRKB409D010170	Colour	WHITE
Odometer	543711 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/70R16	WINDFORCE	6
L/H Front Tyre	245/70R16	WINDFORCE	6
R/H Rear Tyre	245/70R16	LAUFENN	6
L/H Rear Tyre	245/70R16	LAUFENN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/08/2024	Inspection Date	13/08/2024 (11:31)
Survey held at	YEW HOK AUTO SERVICES 1 KAKI BUKIT AVE 6 #02-11 AUTOBAY SINAGPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days