

**AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.**

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)

Tel : 6702 1555 Fax : 6702 1444

Co. Reg No. : 201500047H GST No. : 201500047H

Email : st.sim@autobacs.com.sg

TO	: SMT8203U (CB6392H)	DATE	: 2-Aug-24
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX317G	P -	
		S -	
		L -	
VEHICLE DETAILS			
VEHICLE NO.	: SMT8203U	TOTAL :	
MODEL / MAKE	: HONDA STEPWAGON	L/S -20% :	
CHASSIS NO.	: RP31223524	SUB TOTAL :	
ACCIDENT DETAIL			
DATE	: 31-Jul-24		
TIME	: 06:41HRS	CONTACT PERSON	: MR. SIM 9844 0974

QUOTATION SUMMARY PAGE 01**CLAIMS DETAIL : PARTS LIST**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	Front bumper <i>4 / 350 C47</i>	1	\$ 1,500.00	\$ 1,500.00
2	HL headlamp <i>1/5 CM</i>	1	\$ 2,250.00	\$ 2,250.00
TOTAL PRICE				\$ 3,750.00
LESS -20%				\$ (750.00)
SUB TOTAL PRICE				<u>\$ 3,000.00</u>

QUOTATION SUMMARY PAGE 02**CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING**

TO REMOVE FRONT BUMPER AND TO FACILITATE REPLACEMENT OF PARTS	\$ 300.00	200	
TO RESPRAY FRONT BUMPER	\$ 300.00	200	

TOTAL \$ 600.00**ESTIMATE REPORT**

TOTAL PARTS COST	:	\$ 3,000.00
TOTAL LABOUR COST	:	\$ 600.00
TOTAL REPAIR COST	:	<u>\$ 3,600.00</u>

APPROVED DETAILS

NO. OF REPAIR DAYS

REPAIR UNDER

DATE / TIME OF SURVEY

SURVEYED BY / FROM

LKK Auto Consultants hence notify

the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DAYS

PART BY PART OR LUMP SUM

*Not followed
LKR
normal
2/5 \$2600/
2 days
13/8/24
P- 3600
202
2880
400
3280
22
2600*