

08/11/13) wef
ASS. REC. BY:

REF: CS/A16 24680184/Rup3

5990

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNE 4193

at Workshop m/s PREMIUM

of BENOL SECUR

Insured: AKH

Policy No. 7220007847-02

Claims No. 1490749278SG

Sum Insured: Excess: FBA 800

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 141K

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SNE 4193 Yr Regn: 2022 / Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: AUDI Q2 1.5 TFSI STRONK c.c. 1498

Colour: BLACK AC: Insured / Std / Nil / NA

Sp. Reading: 47546 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: WAW 2226AIMA 035451

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 215/55ZR17

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 10/09/24

Survey held at BENOL

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 14/08/24

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 59K

29/8/24 Rasul confirmed final fig \$10,518.80 (red 9174.20, 46%)

Date/Time, File Pass to?

☐
☐

: Prell. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) : S + RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0607/2024/KS
DATE : 13-Aug-24
WIP : 26710

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/7/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : M/S JALALUDDIN TRAVEL & SERVICES PTE LTD
ADDRESS : BLK 896A TAMPINES STREET 81
#12-854
SINGAPORE 521896
TELEPHONE : HP +65 91006964
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 722007847-02
VEHICLE NO : **SNE 419 J**
MODEL CODE : Q2 1.5 TFSI S-TRONIC
MODEL YEAR : 27/1/2022
ENGINE NO : DPC D33433
CHASSIS NO : WAUZZZGA1MA035451
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Aug-24
PLACE OF ACCIDENT : EAST COAST PARK.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SNE 419 J.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 /	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	S/N \$ 400.00 / 250	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00 / 500	
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,000.00 / 1100	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00 /	
TOTAL LABOUR CHARGES		: \$ 5,852.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 419 J.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>cut</i>	1	\$ 1,575.00	
2	FRONT BUMPER ADAPTOR - RH ?	1	\$ 54.00	
3	FRONT BUMPER TRIM - RH <i>cut</i>	1	\$ 116.00	
4	FRONT BUMPER AIR GUIDE GRILLE- RH <i>cut</i>	1	\$ 114.00	
5	FRONT PARKING AID SENSOR BRACKET - RH X	1	\$ 36.00	
6	FRONT BUMPER LOWER COVER <i>cut</i>	1	\$ 127.00	
7	FRONT BUMPER CLOSING ELEMENT ?	1	\$ 195.00	
8	FRONT WHEEL SPOILER - LH / RH ?	2	\$ 86.00	
9	FRONT BUMPER SPOILER ?	1	\$ 374.00	
10	FRONT BUMPER ADAPTOR - RH ?	1	\$ 54.00	
11	RADIATOR GRILLE X	1	\$ 1,734.00	
12	RADIATOR GRILLE STRIKER PLATE ?	1	\$ 236.00	
13	FRONT BUMPER GUIDE SECTION - RH ?	1	\$ 45.00	
14	LED HEADLIGHT - RH <i>bro</i>	1	\$ 6,915.00	
15	LED HEADLIGHT POWER MODULE - RH ?	1	\$ 904.00	
16	LED HEADLIGHT MOUNTING - RH ?	1	\$ 147.00	
17	LIFT CYLINDER - RH X	1	\$ 170.00	
18	LIFT CYLINDER HOSE - RH X <i>in con</i>	1	\$ 97.00	
19	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 802.00	
20	FRONT NO PLATE X	S/N	\$ 60.00	
TOTAL SPARE PARTS		:	\$ 13,841.00	
TOTAL LABOUR CHARGES		:	\$ 5,852.00	
GRAND TOTAL		:	\$ 19,693.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Rasm - Hp 90010518
: 14/08/24
: 4 days
: excess: TRA
: Present per 54 part

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	599D
Vehicle Details	
Vehicle No.:	SNE419J
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Aug 2024
Vehicle Make:	AUDI
Vehicle Model:	Q2 1.5 TFSI S TRONIC
Primary Colour:	Black
Manufacturing Year:	2021
Engine No.:	DPCD33433
Chassis No.:	WAUZZZGA1MA035451
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$24,924.00
Original Registration Date:	27 Jan 2022
First Registration Date:	27 Jan 2022
Transfer Count:	0
Actual ARF Paid:	\$26,894.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jan 2032
PARF Rebate Amount:	\$20,170.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jan 2032
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$82,001.00
COE Rebate Amount:	\$61,081.00
Total Rebate Amount:	\$81,251.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 14 Aug 2024

OK



Audi Q2 1.5A TFSI S-tronic

\$147,800 Instalment \$1,445/mth

Shortlist

Loan Calculator

Overview Financial Photo Research

Depreciation	\$17,230 / year
Reg. Date	25-May-2022 (7yrs 9mths 10days COE left)
Manufactured	2021
Mileage	23,600 km (10.6k / year)
Transmission	Auto
Engine Cap	1,498 cc
Road Tax	\$684 / year
Power	110.0 kW (147 bhp) View specs of the Audi Q2 (2017)
Curb Weight	1,380 kg
COE	\$95,889
OMV	\$25,321
ARF	\$27,450
Dereg Value	\$95,197 as of today