


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 12.08.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **XE5900J**
MODEL : **ISUZU CYZ52**
DATE OF ACCIDENT : 31.07.2024
TIME OF ACCIDENT : 01:45 HOURS

Veron.

JALCY25ZKLC7000011

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT WINSCREEN RUBBER <i>new</i>	1	\$ 360.00	\$ 360.00
2	FRONT SIDE MIRROR BRACKET <i>Best</i>	1	\$ 974.89	\$ 974.89
3	FRONT SIDE MIRROR ROUND <i>2</i>	1	\$ 294.65	\$ 294.65
4	FRONT SIDE MIRROR (UPPER)	1	\$ 395.73	\$ 395.73
5	FRONT SIDE MIRROR (LOWER) <i>1/2</i>	1	\$ 310.23	\$ 310.23
6	FRONT SIDE MIRROR RH <i>1/2</i>	1	\$ 245.72	\$ 245.72
7	REAR SIDE MIRROR STAND RH	1	\$ 494.52	\$ 494.52
8	FRONT WIPER ARM	3	\$ 349.59	\$ 1,048.77
9	FRONT WIPER LINKAGE	1	\$ 593.16	\$ 593.16
10	BONNET <i>combed</i>	1	\$ 4,629.30	\$ 4,629.30
11	BONNET EMBLEM 'ISUZU' <i>3/2</i>	1	\$ 486.20	\$ 486.20
12	BONNET STICKER (CYZ)	1	\$ 132.00	\$ 132.00
13	BONNET LOCK <i>3/2</i>	2	\$ 385.00	\$ 770.00
14	BONNET LOCK SPRING	2	\$ 152.00	\$ 304.00
15	BONNET HINGE <i>3/2</i>	2	\$ 272.65	\$ 545.30
16	BONNET DAMPER <i>1/2</i>	1	\$ 342.77	\$ 342.77
17	BONNET WEATHERSTRIP <i>1/2</i>	1	\$ 215.41	\$ 215.41
18	BONNET SIDE GRILLE <i>3/2</i>	2	\$ 225.17	\$ 450.34
19	BONNET GRILLE (CENYER) <i>3/2</i>	1	\$ 485.30	\$ 485.30
20	FRONT CORNER PANEL <i>combed</i>	2	\$ 988.80	\$ 1,977.60
21	FRONT CORNER AIR VENT RH <i>combed</i>	1	\$ 427.83	\$ 427.83

825

3210

250

1508

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **XE5900J**
MODEL : **ISUZU CYZ52**
DATE OF ACCIDENT : 31.07.2024
TIME OF ACCIDENT : 01:45 HOURS

22	FRONT CORNER PANEL SILL	2	\$ 36.77	\$ 73.54
23	FRONT CORNER PANEL LOWER BRACKET	2	\$ 138.50	\$ 277.00

67588.47
6450.19

TOTAL PRICE \$ 15,834.26
LESS 15% \$ 2,375.14
SUB TOTAL PRICE \$ 13,459.12

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	BONNET STICKER	1	\$ 250.00	\$ 250.00
2	SIDE VIDEO CAM LH	1	\$ 800.00	\$ 800.00

120

TOTAL \$ 1,050.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,200.00	400
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,000.00	500
3	TO SPRAY TUFF COAT	\$ 550.00	x
4	REMOVE AND REFIX FRONT WINDSCREEN	\$ 180.00	x

900

TOTAL \$ 2,930.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 14,509.12
TOTAL LABOUR COST : \$ 2,930.00
TOTAL REPAIR COST : \$ 17,439.12

Admin Lj
L/s 13/08/24.
03 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP:8297 9787

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 7470.19

L/s: 591K

5.91K