

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 07.08.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLP9983C**
MODEL : **HONDA FREED HYBRID**
DATE OF ACCIDENT : 06.08.2024
TIME OF ACCIDENT : 18:00 HOURS

Hui Rong
2017
GB71012673

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR LH <i>Dented</i>	1	\$ 883.20	\$ 883.20
2	FRONT DOOR OUTER STRIP LH <i>new</i>	1	\$ 82.40	\$ 82.40
3	FRONT DOOR STICKER LH (BLACK) (SET) <i>new</i>	1	\$ 49.20	\$ 49.20
4	FRONT DOOR HINGE LH <i>new</i>	2	\$ 49.80	\$ 99.60
5	FRONT DOOR WEATHER STRIP LH <i>new</i>	1	\$ 94.10	\$ 94.10
6	FRONT DOOR FRAME WEATHER STRIP LH <i>new</i>	1	\$ 89.50	\$ 89.50
7	FRONT DOOR INNER LOCK LH <i>new</i>	1	\$ 228.80	\$ 228.80
8	FRONT DOOR LOCK CATCH LH <i>new</i>	1	\$ 18.10	\$ 18.10
9	FRONT DOOR INNER TRIM BOARD LH <i>new</i>	1	\$ 387.20	\$ 387.20
10	FRONT DOOR POWER WINDOW MOTOR LH <i>new</i>	1	\$ 401.90	\$ 401.90
11	FRONT DOOR REGULATOR LH <i>new</i>	1	\$ 388.00	\$ 388.00
12	FRONT DOOR GLASS CHANNEL LH <i>new</i>	1	\$ 58.90	\$ 58.90
13	FRONT DOOR INNER WATER SHIELD LH <i>new</i>	1	\$ 33.90	\$ 33.90
14	FRONT DOOR SPEAKER LH <i>new</i>	1	\$ 97.20	\$ 97.20
15	ROCKER PANEL RH (OUTER) LH <i>new</i>	1	\$ 383.10	\$ 383.10
16	CENTER PILLAR (OUTER) LH <i>new</i>	1	\$ 864.20	\$ 864.20
17	SLIDING DOOR LH <i>Dented</i>	1	\$ 1,105.40	\$ 1,105.40
18	SLIDING DOOR CENTER ROLLER LH <i>new</i>	1	\$ 96.20	\$ 96.20
19	SLIDING DOOR ALIGN STOPPER OUTER LH <i>new</i>	2	\$ 18.90	\$ 37.80
20	SLIDING DOOR ALIGN STOPPER INNER LH <i>new</i>	2	\$ 19.80	\$ 39.60
21	SLIDING DOOR LOCK LH (FRONT) <i>new</i>	1	\$ 819.40	\$ 819.40
22	SLIDING DOOR LOCK COVER GARNISH LH (FRONT) <i>new</i>	1	\$ 79.20	\$ 79.20

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLP9983C**
 MODEL : **HONDA FREED HYBRID**
 DATE OF ACCIDENT : 06.08.2024
 TIME OF ACCIDENT : 18:00 HOURS

23	SLINDING DOOR LOCK LH (REAR) <i>new</i>	1	\$ 250.60	\$ 250.60
24	SLINDING DOOR LOCK CATCH LH <i>new</i>	2	\$ 129.40	\$ 258.80
25	SLIDING DOOR SENSOR LH <i>lt</i>	1	\$ 437.20	\$ 437.20
26	SLIDING DOOR OUTER STRIP LH <i>new</i>	1	\$ 129.40	\$ 129.40
27	SLIDING DOOR INNER WATER SHIELD LH <i>new</i>	1	\$ 289.30	\$ 289.30
28	SLIDING DOOR STICKER LH (BLACK) (SET) <i>new</i>	1	\$ 42.30	\$ 42.30
29	SLINDING DOOR STEP PANEL GARNISH LH <i>new</i>	1	\$ 355.20	\$ 355.20
30	SLINDING DOOR STEP PANEL LH <i>new</i>	1	\$ 486.70	\$ 486.70
31	SLINDING DOOR LOWER ROLLER PANEL LH <i>new</i>	1	\$ 381.80	\$ 381.80
32	SLINDING DOOR GLASS CHANNEL LH <i>new</i>	1	\$ 169.00	\$ 169.00
33	SLINDING DOOR FRAME WEATHERSTRIP LH <i>new</i>	1	\$ 108.40	\$ 108.40
34	SLIDING DOOR INNER TRIM LH <i>new</i>	1	\$ 892.80	\$ 892.80
35	SLIDING DOOR AUTO SYSTEM MOTOR LH <i>new</i>	1	\$ 921.10	\$ 921.10
36	SLIDING DOOR WIRE HARNESS LH <i>new</i>	1	\$ 120.90	\$ 120.90
37	SLINDING DOOR POWER WINDOW MOTOR LH <i>new</i>	1	\$ 379.40	\$ 379.40
38	SLINDING DOOR SPEAKER LH <i>new</i>	1	\$ 288.10	\$ 288.10
39	SLIDING DOOR REGULATOR GEAR LH <i>new</i>	1	\$ 398.20	\$ 398.20
40	SLINDING DOOR LOWER ROLLER BRACKET LH (UPPER) <i>new</i>	1	\$ 69.40	\$ 69.40
41	SLINDING DOOR LOWER ROLLER LH <i>new</i>	1	\$ 97.80	\$ 97.80
42	SLIDING DOOR ROLLER RAIL LOWER PANEL LH <i>new</i>	1	\$ 84.50	\$ 84.50
43	SLINDING DOOR POWER MOTOR LOCK LH <i>new</i>	1	\$ 488.30	\$ 488.30
44	REAR FENDER LH <i>new</i>	1	\$ 1,082.40	\$ 1,082.40
45	REAR FENDER INNER PANEL LH <i>new</i>	1	\$ 380.20	\$ 380.20
46	REAR FENDER GLASS WITH MOULDING LH <i>new</i>	1	\$ 129.40	\$ 129.40
47	REAR FENDER GLASS FRAME INNER PANEL LH <i>new</i>	1	\$ 284.30	\$ 284.30
48	REAR AXLE <i>new</i>	1	\$ 1,336.20	\$ 1,336.20
49	REAR ABS SENSOR <i>new</i>	2	\$ 198.20	\$ 396.40
50	REAR SHOCK ABSORBER <i>new</i>	2	\$ 213.90	\$ 427.80
51	REAR WHEEL HUP WITH BEARING <i>new</i>	2	\$ 410.80	\$ 821.60
52	TAIL LAMP LH <i>new</i>	1	\$ 669.80	\$ 669.80
53	REAR BUMPER <i>new</i>	1	\$ 608.20	\$ 608.20
54	REAR BUMPER SIDE BRACKET <i>new</i>	2	\$ 16.70	\$ 33.40
55	REAR BUMPER SIDE RETAINER UPPER <i>new</i>	2	\$ 28.20	\$ 56.40
56	REAR BUMPER SIDE RETAINER LOWER <i>new</i>	1	\$ 39.50	\$ 39.50

710.

45

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLP9983C**
 MODEL : **HONDA FREED HYBRID**
 DATE OF ACCIDENT : 06.08.2024
 TIME OF ACCIDENT : 18:00 HOURS

57	REAR BUMPER REFLECTOR LH <i>new</i>	1	\$ 49.50	\$ 49.50	<i>+</i>
58	FRONT EXHAUST DOWN PIPE WITH CATALYTIC CONVERTER <i>new</i>	1	\$ 1,332.40	\$ 1,332.40	<i>+</i>

6839-90
5471-92

TOTAL PRICE \$ 20,633.60
 LESS 20% \$ 4,126.72
SUB TOTAL PRICE \$ 16,506.88

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT DOOR SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
2	FRONT DOOR INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
3	SLIDING DOOR SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
4	SLIDING DOOR INNER TRIM CLIP <i>new</i>	1	\$ 60.00	\$ 60.00	<i>30</i>
5	REAR FENDER SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
6	REAR FENDER GLASS SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
7	REAR FENDER GLASS INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	<i>20</i>
8	REAR FENDER GLASS SOLAR FILM <i>new</i>	1	\$ 350.00	\$ 350.00	<i>+</i>
9	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
10	WHEEL TYRE <i>new</i>	4	\$ 480.00	\$ 1,920.00	<i>+</i>
11	WHEEL RIM (SET) <i>cut</i>	1	\$ 1,800.00	\$ 1,800.00	<i>480</i>
12	BRAKE OIL <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>

680

TOTAL \$ 4,880.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	<i>1200</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>1000</i>
3	TUFF COAT	\$ 450.00	<i>80</i>
4	WIRING CHECK	\$ 280.00	<i>30</i>
5	CONDUCT WATER LEAKAGE TEST	\$ 150.00	<i>X</i>
6	TRANSFER FRONT DOOR MECHANISM	\$ 160.00	<i>40</i>

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLP9983C**
 MODEL : **HONDA FREED HYBRID**
 DATE OF ACCIDENT : 06.08.2024
 TIME OF ACCIDENT : 18:00 HOURS

7	REMOVE AND REFIX DOOR WINDOW	\$ 200.00	40
8	RESET ABS LIGHT	\$ 350.00	x
9	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 550.00	60
10	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	x
11	FOUR WHEEL ALIGNMENT	\$ 120.00	80
12	TRANSFER REAR SLIDING DOOR MECHANISM	\$ 160.00	80
13	RESET SLIDING DOOR SYSTEM	\$ 550.00	180
14	REMOVE AND REFIX REAR FENDER GLASS	\$ 100.00	50
15	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
16	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 80.00	60
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 480.00	x

2850

TOTAL \$ 8,160.00

TOTAL PARTS COST : \$ 21,386.88

TOTAL LABOUR COST : \$ 8,160.00

TOTAL REPAIR COST : \$ 29,546.88

Adnan Lj
2/8 13/08/24

08 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

total: 9101.92

C/S: 7250 ✓