

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN	CE LTD	Ref:	CS/INC24080189/Anh3m4	
	75 BRAS BASAH ROAD NCOME CENTRE SINGAPORE 189557		Date:	20/11/2024	
	INCOME CENTRE	SINGAPORE 189557	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBR 7076S	Veh. Inspected	SND 4062H	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1290155-001	Excess	\$0.00	
	Assign From	YEE PEI LI	Assign Date	13/08/2024	
2. Vehicle Details					
_	Make & Model	MERCEDES BENZ CLA180	C.C	1595	
	Engine No.	27091030511662	Year of Reg.	13/01/2015	
	Chassis No.	WDD1173422N143287	Colour	YELLOW	
	Odometer	197587 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	225/40R18	PIRELLI	6	
	L/H Front Tyre	225/40R18	PIRELLI	6	
	R/H Rear Tyre	225/40R18	PIRELLI	6	
	L/H Rear Tyre	225/40R18	PIRELLI	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.					
DAN	IAGES SEE DETAIL	S.			
5.	General Information				
	Accident Date	07/08/2024	Inspection Date	13/08/2024 (15:04)	
	Survey held at  JL PERFECT AUTOWORK PTE LTD  8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days					