

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

Not Authorized

13 June 2024

REG NO. : SLC 4188 H
MAKE/MODEL : TOYOTA CAMRY

14/6/24
16,600
15 days

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION LIST ITEMS	AMT(S\$)
1	Front door -RH Body	\$ 2408.10 2,746.50 ✓
1	Front door checker su	\$ 80.00 X
2	Front door hinges su	\$ 190.00 X
1	Front door glass moulding tw	\$ 185.50 ✓
1	Front door inner board Dis/To	\$ 850.90 ✓
1	Front door lock Dange/JM	\$ 509.00 ✓
1	Front door outer handle n	\$ 395.00 X
1	Front door regulator Bnt	\$ 305.50 ✓
1	Front door regulator motor JM	\$ 509.00 ✓
1	Front door rubber To	\$ 230.50 ✓
1	Front door step garnish DE	\$ 166.50 ✓
1	Front door black tape n	\$ 120.00 ✓
1	Centre pillar RM Body	\$ 595.10 ✓
1	Centre pillar inner trim - top NS	\$ 154.34 X
1	Centre pillar inner trim - lower Dis	\$ 195.80 ✓
1	Rocker panel -RH Body	\$ 855.70 ✓
1	Rocker panel side skirt Dis	\$ 750.70 ✓
1	Side air bag sensor NS	\$ 719.70 X
1	Air bag control unit sensor assy Actuated	\$ 1820 3,027.20 ✓
1	Front safety belt assy Dange/CN	\$ 1,812.40 ✓
1	Front seat headrest assy n	\$ 1,818.40 X
1	Front seat with air bag assy Actuated / Bnt	\$ 4304.90 7,522.50 ✓
1	Rear door -RH Body	\$ 2201.10 2,386.30 ✓
1	Rear door checker tw	\$ 80.00 ✓
1	Rear door glass outer moulding tw	\$ 200.30 ✓
2	Rear door hinges Bnt/JM	\$ 190.00 ✓
1	Rear door inner board Dis/To	\$ 850.90 ✓
1	Rear door lock Dange/JM	\$ 509.00 ✓
1	Rear door regulator Bnt	\$ 305.50 ✓
1	Rear door regulator motor JM	\$ 288.70 ✓
1	Rear door rubber To	\$ 235.50 ✓
1	Rear door black tape n	\$ 120.00 ✓
1	Rear Sport rim o/s C47	\$ 987.70 ✓
		\$ 29,894.14
	Less 25%	\$ 7,473.54
		\$ 22,420.61

S/N

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	20
2	To remove and refit inner garnishes.	\$	180.00	60
3	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door. and air bag system	\$	500.00	300
4	To apply undercoating.	\$	200.00	80
5	Panel beating.	\$	1,600.00	1500
6	To re-spray painting on the affected areas.	\$	1,500.00	1300
		\$	4,060.00	

GRAND TOTAL :**\$ 26,480.61**

P-23383.50
 252
 P 17537.62

L-3260
 20797.62
 203
 16638.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

23383.5

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

25 June 2024

REG NO. : SLC 4188 H
MAKE/MODEL : TOYOTA CAMRY

SUPPLEMENTARY ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

<u>QTY</u>	<u>DESCRIPTION</u>	<u>AMT(S\$)</u>
	<u>LIST ITEMS</u>	
1	Centre console box assy <i>See</i>	\$ 3,674.50 x
1	Centre console panel sub-assy <i>See</i>	\$ 3,193.20 x
1	Roof top panel inner trim board <i>warped / See</i>	\$ 1,875.20 ✓
		<u>\$ 8,742.90</u>
	Less 25%	<u>\$ 2,185.73</u>
		<u>\$ 6,557.18</u>

GRAND TOTAL :

\$ 6,557.18