(08/11/13) Wef	
ASS. REC. BY: Pacal REF: CS FC	24060102 Uvh3
ASSI	GNMENT
From: Date:	Veh No: 52 C 4/FS// Yr Regn: 26/09/08
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD /TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SLC 4/884	Make: Toyoto comy c.c 2362
at Workshop m/s W.L. Sc/acc	Colour Cony A/C: Insured / Std / NI / NA
of	Sp.Reading 236784 T/Radio: Insured / Std / NI / NA
Insured: SMA 42847	Eng/No:
Policy No.	CNO: MROS3BK 4007029387
Claims No. D24005280MFCT	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Indeder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F:
(Policy Condition) Permark: The yell had commenced its N/S O/S	BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
Remark: The veh had commenced its repair at the time of inspection.	
	000/0
0 11 10 V No	R/Bal. Rear R/Bal. mm
IDAO Accident riport.	L/Bal. 6 mm L/Bal. 6 mm
16- De Veren No.	D.O.A. 12/105/24 D.O.I. 14/6/24
Est. Repairs: / days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No	Survey held at
09.27	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	0/5 Bocky
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction Dog / 0 / .	11 711/2 61
() e une 3-09-2018 87	828713
70/ 4 yrg. 20014. 100/1	4011)
18/12/ 1/5 \$ 16,600 informa.	Lowrenz (red 16,437.79, 49%)
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 15
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fee	
Bound Formation	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others : Weekend (\$)
Lump Sum / I.B.I: (\$: vveekend (♥)
	TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	090J
Vehicle No.:	SLC4188H
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jun 2024
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.4 AUTO ABS AIRBAG
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	2AZE112219
Chassis No.:	MR053BK4007029382
Maximum Power Output:	123.0 kW (164 bhp)
Open Market Value:	\$27,261.00
Original Registration Date:	26 Sep 2008
First Registration Date:	26 Sep 2008
Transfer Count:	3
Actual ARF Paid: Intended PARF Rebate Details	\$27,261.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	25 Sep 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$33,377.00
COE Rebate Amount:	\$14,287.00
Total Rebate Amount: Message	\$14,287.00
You will not be eligible for any COE rebate from the your enew your COE.	he current COE (including unused COE from any lay-up period/s), if

The information contained herein is correct as at 14 Jun 2024

sacarmart

Login |Sign Up

New Used Electric Loan Rent Sell Directory e-Shop Insurance Articles Forum Resource

Post an Advertisement Sell it yourself! Advertise it at just \$72 until it's SOLD!

Ways of Selling

ow Interest Rate In-House Loan by GV Cars Financing



Flexible Financing Options by GV Cars Financing at 2.98% GV Cars Financing StarAd



Sort by Date Posted 🗸 20 🗸 results/page

11 vehicles

Post an Ad

Advertiser Login

	0									
	TOYOTA CAMRY 2028				Any Category		Advanced Search	C Search		
	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status	
Search Selection	TOYOTA CAMRY	2028	Any	Any	> 10 year(s) old	Any	Any	Any	Available	
	Toyota Can	nry 2.0A (COE till		N.A	24-Jul-2008	1,998 cc	-	Luxury	Available	



Auction Closing Time: 19th Jun 2024 at 01:00 PM

With key, viewing date: 13/06/2024, 14/06/2024 and 18/06/2024, time: 9:00 am to 5:00 pm (weekdays only), no viewing on Saturdays, Sundays, public holidays & tender closing date.

Posted: 12-Jun-2024



Toyota Camry 2.0A (COE till \$48,800 \$10,930 /yr 17-Jan-2009 1,998 cc Luxury Available 11/2028)

Market lowest depreciation. Super spacious interior. All wear and tears fixed. Contact us today to schedule for a viewing! Flexible 100% in house loan/bank loan available. Trade in welcomed!

Cars Consignment Pte Ltd

Posted: 11-Jun-2024



Toyota Camry 2.0A (COE till 11/2028)

\$51,800

\$11,620 /yr

28-Nov-2008

135,000 km

Luxury

Available

AUCTION

Workshop check welcome, Full loan mthly at \$1194 only, Trade in with high flexible loan available, well maintained by previous owner with beautiful interior. All our listed vehicles has undergone a 120 points check by zen auto before pur...

Posted: 10-Jun-2024



Toyota Camry 2.4A (COE till \$46,800 \$11,840 /yr 28-May-2008 2,362 cc Luxury Available

05/2028)

Well Maintained Unit, All wear and tear done up with receipt proof. No admin fees. No gimmicks/hidden costs. Bank loan from 2.78%. Full/PHV loan available. High trade-in guaranteed! Immediate transfer of ownership. Kindly contact o...

Posted: 09-Jun-2024



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Camry 2.4A G (COE till \$47,000

08/2028)

\$11,330 /yr

07-Aug-2008

2.362 cc

Luxury

Available

Efizzig motor traders. 100% loan, immediate approval! no repairs needed. Silent undercarriage, wear and tear parts replaced, excellent condition! All trade in are welcome. Act now! Call us now for viewing and test drive.

Posted: 08-Jun-2024

Compare

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com Mobile: +65 9009 6622

13 June 2024

REG NO.:

SLC 4188 H

MAKE/MODEL: TOYOTA CAMRY

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

DESCRIPTION LIST ITEMS 1 Front door -RH 30 50 2,746.50 1 Front door checker 50 80.00 x 190.00 x 1 190.00 x 195.50 1 Front door linges 50 509.00 1 Front door lock 50 509.00 1 Front door lock 50 509.00 1 Front door lock 50 509.00 1 Front door regulator 50 509.00 1 Front door lack tape 70 70 70 70 70 70 70 7	OTV	DECODIPTION			
Front door -RH	QIY				AMT(S\$)
Front door checker \$\text{\$000 pt} \$\text{\$190.00 pt} \$\text{\$190.00 pt} \$\text{\$190.00 pt} \$\text{\$190.00 pt} \$\text{\$185.50} \$\text{\$190.00 pt} \$\text{\$185.50} \$\text{\$190.00 pt} \$\text{\$185.50} \$\text{\$190.00 pt} \$\text{\$190.00 pt}	1	3 /:		0) 1/00/10	0.740.50
Front door hinges \$ 190.00 x	1777.				
Front door glass moulding Twi services and the services are serviced as the serviced as the services are serviced as the serviced as	100				
Front door inner board	1				
Front door lock Portion \$ 509.00 Front door outer handle	1				
Front door outer handle front door regulator fund some state of the first door step garnish fund state fund some state of the first door black tape fund some st	1				
Front door regulator \$ 305.50	1	1 /0			
Front door regulator motor	1				
Front door rubber Front door step garnish Front door step garnish Centre pillar AH Centre pillar inner trim - tower Rocker panel -RH Rocker panel side skirt Air bag control unit sensor assy Front safety belt assy Front seat with air bag assy Rear door -RH Rear door checker Rear door inner board Rear door regulator Rear door regulator Rear door regulator Rear door rubber S S S S S S S S S S S S S	1				and the same of th
Front door step garnish Front door black tape Centre pillar AM Centre pillar AM Centre pillar inner trim - top Rocker panel -RH Rocker panel -RH Rocker panel side skirt Side air bag sensor Air bag control unit sensor assy Front safety belt assy Front seat with air bag assy Rear door -RH Roar door checker Rear door checker Rear door lock Rear door lock Rear door lock Rear door regulator Rear door black tape Rear door bl	1				
Front door black tape Centre pillar PM Centre pillar inner trim - top Centre pillar inner trim - top Rocker panel -RH Rocker panel side skirt Side air bag sensor Air bag control unit sensor assy Front safety belt assy Front seat with air bag assy Rear door -RH Rear door checker Rear door inner board Rear door regulator Rear door regulator Rear door regulator Rear door black tape Marker Sold Marker S	1				230.50
Centre pillar PM	1	Service Service			166.50
Centre pillar inner trim - top	1			\$ 80	120.00 —
Centre pillar inner trim - lower Ds Rocker panel -RH Rocker panel side skirt Rocker panel side skirt Side air bag sensor Air bag control unit sensor assy Front safety belt assy Part / Cro Front seat with air bag assy Rear door -RH Rear door checker Rear door locker Rear door inner board Rear door regulator Rear door black tape Rear door black tape Rear Sparf rim off Cyl Substitute Subst	1			\$	595.10
Rocker panel -RH Rocker panel side skirt Rocker panel side store Rocker panel store Rocker panel side store Rocker panel side store Rocker panel side store Rocker panel store Rocker p	1	the state of the s		\$	154.34 X
Rocker panel side skirt Side air bag sensor NS Air bag control unit sensor assy Air bag control unit sensor assy Front safety belt assy Front seat headrest assy Rear door -RH Rear door checker Rear door glass outer moulding Rear door inner board Rear door regulator Rear door regulator Rear door regulator Rear door black tape Rear Scart cim of CA1 Side air bag sensor NS NATION \$ 1,812.40 \$ 1,818.40 \times \$ 1,	1	Centre pillar inner trim - lower Dy		\$	195.80
Side air bag sensor Air bag control unit sensor assy April 1 Front safety belt assy Front seat headrest assy Front seat with air bag assy Rear door -RH Rear door checker Rear door glass outer moulding Rear door inner board Rear door lock Rear door regulator Rear door regulator Rear door regulator Rear door black tabe Rear door black tabe Rear Specifician of CAI Side air bag sensor NS 719.70 \$ 1,812.40 \$ \$ 1,812.40 \$ \$ 1,812.40 \$ \$ \$ 1,812.40 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	1	Rocker panel -RH		\$	855.70
Air bag control unit sensor assy Application \$ 1,820 3,027.20	1	Rocker panel side skirt		\$	750.70 —
Front safety belt assy Part / Cros \$ 1,812.40	1	Side air bag sensor		\$	719.70 ×
Front safety belt assy Part Cos S 1,812.40	1	Air bag control unit sensor assy Aarth		\$ 1820	3,027.20
Front seat headrest assy 1	1	Front safety belt assy Day (CA)			The same of the sa
Front seat with air bag assy Actual Bul S 1/30 1/30 7,522.50 Rear door -RH Bold Bul S 1/201.10 2,386.30 Rear door checker Tuy S 80.00 Rear door glass outer moulding Tuy S 200.30 Rear door inner board D 1/5 Toy S 850.90 Rear door lock S 1/201 S 850.90 Rear door regulator Bul S 305.50 Rear door regulator motor Juy S 288.70 Rear door lock S 235.50 S 29,894.14 Rear S 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1	Front seat headrest assy 11			
1 Rear door -RH	1	Front seat with air bag assy Actual / But		\$ = 4304.90	72
Rear door checker	1	Rear door -RH 3. d5,79		\$2201.10	
Rear door glass outer moulding 190.00 190.	1	Rear door checker		\$	The same of the sa
Rear door hinges 190.00 1 Rear door inner board 190.00 1 Rear door lock 190.00 1 Rear door regulator 190.00 1 Rear door regulator 190.00 1 Rear door regulator motor 190.00 1 Rear door rubber 190.00 1 Rear door black tape 190.00 1 Rear 190.00 190.00 288.70 190.00 3 288.70 4 29.894.14 5 29.894.14	1	Rear door glass outer moulding		\$	
Rear door inner board D/s/Tom \$ 850.90 Rear door lock Supplies \$ 509.00 Rear door regulator Supplies \$ 305.50 Rear door regulator motor JM \$ 288.70 Rear door rubber Join \$ 235.50 Rear door black tape July \$ 120.00 Rear Spart rim of Cup \$ 29,894.14 Less 25% \$ 7,473.54	2			\$	
1 Rear door lock 509.00 1 Rear door regulator 3M \$ 305.50 1 Rear door regulator motor 3M \$ 288.70 1 Rear door rubber 1000 \$ 235.50 1 Rear door black tape 3M \$ 120.00 1 Rear \$700 (1m 0)	1			\$	
1 Rear door regulator	1	Rear door lock		39.3	
1 Rear door regulator motor 1 Rear door rubber 1 Rear door black tape 1 Rear Sγ or f rim of CHγ 1 Ress 25% \$ 288.70	1	Rear door regulator 3M4			
1 Rear door rubber 10/10 1 Rear door black tape 10/10 1 Rear Sport rim of CH1 \$ 235.50 \$ 120.00 \$ 987.70 \$ 29,894.14 Less 25% \$ 7,473.54	1	Rear door regulator motor JM			
1 Rear door black tape 120.00 1 Rear Spart rim of Cup \$ 20.00 \$ 987.70 \$ 29,894.14 Less 25% \$ 7,473.54	1				
1 Rear Sport rim of CH1 \$ 987.70 \$ 29,894.14 Less 25% \$ 7,473.54	1	Rear door black tape		\$ 80	
\$ 29,894.14 Less 25% \$ 7,473.54	1			*	
Less 25% \$ 7,473.54				The same of the sa	
			Less 25%	<i>*</i>	
			2000 20 /0		22,420.61

S/N	LABOUR CHARGES	
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes.	\$ 180.00 60
3	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door. and one for system	\$ 500.00 300
4	To apply undercoating.	\$ 200.00 80
5	Panel beating.	\$ 1,600.00 /500
6	To re-spray painting on the affected areas.	\$ 1,500.00 /300
		\$ 4,060.00

GRAND TOTAL:

\$ 26,480.61

P-2338350 2527 73.57.62

20787-62 20787-62 203 16638.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883 wegarage@consultant.com Mobile: +65 9009 6622

25 June 2024

REG NO.:

SLC 4188 H

MAKE/MODEL: TOYOTA CAMRY

SUPPLEMENTARY ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION			AMT(S\$)
	LIST ITEMS			
1	Centre console box assy	8u		\$ 3,674.50 €
1	Centre console panel sub-assy	Su		\$ 3,193.20°
1	Roof top panel inner trim board	worped De		\$ 1,875.20
				\$ 8,742.90
			Less 25%	\$ 2,185.73
				\$ 6.557.18

GRAND TOTAL:

\$ 6,557.18