

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHEN ZHENWU
114 WOODLANDS AVE 5 #08-31
SINGAPORE 739017

Contact : 93899827

TAX INVOICE

Repair Code : CLM16387

Date in : 12/08/2024

Vehicle Num. : SMC4030S

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400029698/2ZR0B81234

TP INC

VERON.

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dehnd</i>	1	596.00	✓ 596.00
REAR BUMPER END SEAL COVER L/R <i>RH Dehnd</i>	2	92.30	<i>92.30</i> 184.60
REAR BUMPER REFLECTOR L/R <i>from LH Cmkld</i>	2	78.00	<i>78</i> 156.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	98.00	+ 196.00
REAR END PANEL <i>Dehnd</i>	1	781.45	✓ 781.45
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	148.00	+ 148.00
REAR END PANEL INNER TOP GARNISH <i>Dehnd</i>	1	287.90	✓ 287.90
REAR FENDER INNER TRIM GARNISH L/R <i>from LH Dehnd</i>	2	656.00	<i>656</i> 1,312.00
REAR FLOOR PANEL TOP BOARD COVER <i>from Cmkld</i>	1	418.60	✓ 418.60
REAR FLOOR PANEL TRAY <i>Cmkld</i>	1	575.40	<i>346</i> 575.40
REAR LH FENDER <i>Regis</i>	1	896.00	+ 896.00
REAR LH FENDER GLASS WITH MOULDING <i>new</i>	1	496.00	✓ 496.00
REAR LH FENDER INNER AIR VENT <i>from LH Dehnd</i>	1	105.00	✓ 105.00
REAR TAILGATE <i>Dehnd</i>	1	929.60	✓ 929.60
REAR TAILGATE 'HYBRID' EMBLEM <i>new</i>	1	50.00	✓ 50.00
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	50.00	+ 50.00
REAR TAILGATE 'PRIUS' EMBLEM <i>new</i>	1	52.30	✓ 52.30
REAR TAILGATE DAMPER L/R <i>new</i>	2	255.00	+ 510.00

*** This is a computer-generated document which requires no signature.***

aki Bukit AutoHub
Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHEN ZHENWU
114 WOODLANDS AVE 5 #08-31
SINGAPORE 739017

Contact : 93899827

TAX INVOICE

Repair Code : CLM16387

Date in : 12/08/2024

Vehicle Num. : SMC4030S

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400029698/2ZR0B81234

REAR TAILGATE HINGES L/R	2	93.00	+ 186.00
REAR TAILGATE INNER GARNISH	1	578.00	✓ 578.00
REAR TAILGATE INNER RUBBER STOPPER L/R	2	29.00	+ 58.00
REAR TAILGATE MECHANISM LOCK	1	425.00	✓ 425.00
REAR TAILGATE WEATHER STRIP	1	300.70	✓ 300.70
REAR TAILGATE WINDSCREEN LOWER SEAL	1	42.00	✓ 42.00
REAR TAILGATE WINDSCREEN MOULDING L/R	2	65.00	✓ 130.00
REAR TAILGATE WINDSCREEN UPPER SEAL	1	38.00	✓ 38.00
REAR TAILLAMP L/R	2	691.40	✓ 1,382.80
REAR TAILLAMP LOWER BRACKET L/R	2	68.00	✓ 136.00

Subtotal before discount

11,021.35

Percentage discount 25%

2,755.34

Sub-total 1

8,266.01

REAR BUMPER CLIPS - SET	1	50.00	30 50.00
REAR BUMPER REVERSE SENSOR	1	250.00	200 250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	20 30.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET	2	50.00	+ 100.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	1	50.00	30 50.00

*** This is a computer-generated document which requires no signature.***

I aki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHEN ZHENWU
114 WOODLANDS AVE 5 #08-31
SINGAPORE 739017

Contact : 93899827

TAX INVOICE

Repair Code : CLM16387

Date in : 12/08/2024

Vehicle Num. : SMC4030S

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400029698/2ZR0B81234

REAR TAILGATE OUTER GARNISH CLIPS - SET	340	1	30.00	30.00
REAR TAILGATE WINDSCREEN SEALANT		1	80.00	80.00
Subtotal before discount				590.00
Percentage discount 0%				0.00
Sub-total 2				590.00
Parts-total				8,856.01

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	80.00
To remove, reinstall tailgate windscreen	120 150.00
To remove, reinstall fender glass	120.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60 100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	80 1,300.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1000 1,400.00
To apply anti-rust chemical on repaired and replaced panel.	60 120.00
To remove, reinstall tailgate mechanism and check for function	60 80.00
Labour Total	3,350.00
Parts & Labour Total	12,206.01

*** This is a computer-generated document which requires no signature.***

Adrian L
2/5 14/08/24

08 Days
Total 8498.73
L/S: 6.7K ✓