

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	ALLIED WORLD AS	SURANCE COMPANY LTD	Ref:	CS3/AWA24080192/Eqp3	
	(SINGAPORE BRANCH)		Date:	22/08/2024	
	60 ANSON ROAD #0		Code:	AWA	
1	MAPLETREE ANSON SINGAPORE 079914 Code: AWA  1. Policy Particulars :- PRE-REPAIR SURVEY				
l	Insured Veh.	YN 1096Y	Veh. Inspected	GBG 7255A	
	Policy No.	BVFCSB0013842302	Coverage	0	
	Claim No.	CSG24VFC2A00018/HLF	Excess	\$0.00	
	Assign From	PEGGY CHAN	Assign Date	13/08/2024	
2. Vehicle Details					
	Make & Model	TOYOTA HIACE DX 3.0 MANUAL	C.C	2982	
l	Engine No.	1KD2744393	Year of Reg.	09/10/2017	
	Chassis No.	KDH2010231605	Colour	SILVER	
	Odometer	192570 KM	Steering	IN ORDER	
l	Brakes	IN ORDER	General	FAIR	
	Modification(s)	RIMS: STANDARD ALLOY RIM	•		
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	195R15C	YOKOHAMA	5	
l	L/H Front Tyre	195R15C	YOKOHAMA	5	
l	R/H Rear Tyre	195R15C	YOKOHAMA	5	
	L/H Rear Tyre	195R15C	YOKOHAMA	5	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5. General Information					
l	Accident Date	10/08/2024	Inspection Date	13/08/2024 (11:35)	
	Survey held at	56 LOYANG WAY - REPAIRER: SE AUT	OHUB PTE LTD		
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.					
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.					
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b. Estimate Days of Repair  ESTIMATED NORMAL REPLODE OR REDAIR: 4 Working Days					
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

## CTY

## STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.