



Borneo Motors



Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No.2 Pandan Crescent
 Singapore 128462, Tel no. : 6631 1388

ESTIMATE

Account Details		Account No.		Customer Details			
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS		Mr Yeo Boon Kwang 60 Pemimpin Terrace Singapore 575967 Mobile: 90108040			
		Document No. 0					
		Document Date 13/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AGL25R	AWTGZ L2	29/12/2017	SCX0060P	0	24775	77/OD/SCX0060P
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTJBAMCA102040798		8ARW686428	60	Cheng Wei Ting	--/--/----	0.00	--/--/----
L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: MPC23A00385000 ACC DATE:24/07/2024 TOW/DRIVE IN:25/07/2024 EXCESS:500.00\$ DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON: EST TO CHECK WIRING AND CONDUCT WATER LEAK T					50 108.00
2	B	BP-LAB3 TO REMOVE AND REINSTALL REAR BUMPER SENS					192.00
3	B	BP-LAB3 TO REMOVE AND REINSTALL REAR BUMPER SENS					192.00
4	B	BP-ECU3 TO RESET ECU & REPROGRAMME					192.00
5	B	BP-MECH3 TO CONDUCT ADJUSTMENT ON REAR BLINDSPO					192.00
6	B	BP-LAB3 TO REMOVE AND REINSTALL REAR SEAT AND IN <i>ph</i>					768.00
7	B	BP-MECH3 TO REPLACE TYRE RIM AND CONDUCT WHEEL BA					192.00
8	B	BP-MECH3 TO CONDUCT WHEEL ALIGNMENT ADJUSTMENT					192.00
9	B	BP-WS3 RENEW REAR RHS QUATER GLASS					384.00
For & on behalf of		Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due	

Customer Copy



Borneo Motors



Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No 2 Pandan Crescent
 Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details		Account No.		Customer Details			
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS		Mr Yeo Boon Kwang 60 Pemimpin Terrace Singapore 575967			
		Document No. 0					
		Document Date 13/08/2024		Mobile: 90108040			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AGL25R	AWTGZ L2	29/12/2017	SCX0060P	0	24775	77/OD/SCX0060P
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTJBAMCA102040798		8ARW686428	60	Cheng Wei Ting	0.00		--/--/----
L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
10	S	BP-SUBLET TO SUPPLY & INSTALL QUATER GLASS 3M SOLA R FILM		1.00	108.00	30.00	230.00
11	B	BP-LAB3 TO REMOVE AND REINSTALL BOTH RHS'S DOOR COMPONENTAND MECHANISM TO NEW DOOR		1.00	200.00	30.00	1536.00
12	Z	BP-SLANT SUPPLY SEALANT (NETT)		1.00	267.20	30.00	200.00
13	B	BP-LAB3 TO REPLACE AND REPAIR ON ACCIDENT AFFECT ED AREA		20.00	2.20	30.00	4608.6144.00
14	B	BP-RES3 TO SPRAY PAINTING ON ACCIDENT AFFECTED A REA		20.00	2.80	30.00	1958.43916.80
15	1	T21000-20 SIKA 182010 SIKA TACK GO! (BLA		1.00	108.00	30.00	75.60
16	2	T21000-22 SIKA 207. G+P ADHESIVE PRIMER		1.00	200.00	30.00	140.00
17	3	T08826-08115 PANEL BONDING AD		1.00	267.20	30.00	187.04
18	4	L90269-04051 RIVET		20.00	2.20	30.00	30.80
19	5	T90269-06013 RIVET		20.00	2.80	30.00	39.20
20	6	L52159-48931 COVER, RR BUMPER		1.00	1582.60	30.00	1107.82
21	7	L61601-48050 PANEL SUB-ASSY, LINER, RR WHEEL		1.00	2639.00	30.00	1847.30
22	8	L65637-48070 DUCT SUB-ASSY, WINDOW ASSY, FR		1.00	493.60	30.00	345.52
23	9	L62904-48030 WINDOW ASSY, FR		1.00	213.20	30.00	149.24
24	0	L62710-48310 PANEL SUB-ASSY, FR		1.00	392.80	30.00	274.96
25	1	L67001-48160		1.00	3614.30	30.00	2530.01
For & on behalf of				Total			
Borneo Motors (Singapore) Pte Ltd				Charge Summary			
Please acknowledge receipt of vehicle				Parts			
				Labour			
				Sublet			
				Lubrication/Fluid			
				Others			
				Less			
				Amount Due			

Customer Copy



Borneo Motors



Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details		Account No.		Customer Details	
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS		Mr Yeo Boon Kwang 60 Pemimpin Terrace Singapore 575967	
		Document No. 0			
		Document Date 13/08/2024		Mobile: 90108040	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AGL25R	AWTGZ L2	29/12/2017	SCX0060P	0	24775	77/OD/SCX0060P

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTJBAMCA102040798	8ARW686428	60	Cheng Wei Ting	0.00	--/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
26	2	L67861-48110 WEATHERSTRIP, FR <i>Xm</i>	1.00	392.80	30.00	274.96
27	3	L75921-48060 TAPE, BLACK OUT, <i>nu</i>	1.00	23.10	30.00	-16.17
28	4	L75985-48050 STRIPE, FR DOOR, <i>nu</i>	1.00	95.60	30.00	-66.92
29	5	L75965-48010 STRIPE, FR DOOR, <i>nu</i>	1.00	38.00	30.00	-26.60
30	6	L68610-48080 CHECK ASSY, FR DOOR, <i>Xm</i>	1.00	381.60	30.00	267.12
31	7	L67003-48190 PANEL SUB-ASSY, RR <i>nu</i>	1.00	3194.80	30.00	2236.36
32	8	L67871-48080 WEATHERSTRIP, RR <i>Xm</i>	1.00	347.00	30.00	242.90
33	9	L75987-48050 STRIPE, RR DOOR, <i>nu</i>	1.00	45.80	30.00	-32.06
34	0	L75987-48070 STRIPE, RR DOOR, <i>nu</i>	1.00	60.60	30.00	-42.42
35	1	L75953-48030 STRIPE, RR DOOR, <i>nu</i>	1.00	52.80	30.00	-36.96
36	2	L67895-48041 TAPE, BLACK OUT RR <i>nu</i>	1.00	58.10	30.00	-40.67
37	3	L67857-48032 WEATHERSTRIP, RR <i>nu</i>	1.00	200.80	30.00	140.56
38	4	L68630-48080 PROTECTOR, RR DOOR <i>nu</i>	1.00	381.60	30.00	267.12
39	5	L75071-48100 CHECK ASSY, RR DOOR <i>Xm</i>	1.00	761.60	30.00	533.12
40	6	L75075-48140 MOULDING SUB-ASSY, <i>nu</i>	1.00	600.20	30.00	420.14
41	7	L75077-48010 MOULDING SUB-ASSY, <i>nu</i>	1.00	126.20	30.00	88.34
42	8	L75605-48020 MOULDING SUB-ASSY, <i>nu</i>	1.00	194.10	30.00	135.87
43	9	L75873-48020 MOULDING SUB-ASSY, <i>nu</i>	1.00	97.60	30.00	68.32
44	0	L75850-48040 MOULDING, QUARTER <i>nu</i>	1.00	761.60	30.00	533.12
45	1	L75867-30120 MOULDING ASSY, BODY <i>Xm</i>	1.00	15.10	30.00	147.98
		CLIP, ROCKER PANEL <i>nu</i>	14.00			

For & on behalf of		Customer's Signature		Charge Summary	
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Total	
				Less	
				Amount Due	



Borneo Motors



Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details		Account No.		Customer Details	
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS		Mr Yeo Boon Kwang 60 Pemimpin Terrace Singapore 575967	
		Document No. 0			
		Document Date 13/08/2024		Mobile: 90108040	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AGL25R	AWTGZ L2	29/12/2017	SCX0060P	0	24775	77/OD/SCX0060P
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In	Collected On	
JTJBAMCA102040798		8ARW686428	60	Cheng Wei Ting	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
46	2	L75857-48010 COVER, ROCKER PANEL	4.00	5.40	30.00	15.12
47	3	L75865-48040 PROTECTOR, ROCKER	1.00	60.50	30.00	42.35
48	4	L75755-48040 MOULDING, FR DOOR	1.00	104.30	30.00	73.01
49	5	L75707-48030 MOULDING SUB-ASSY,	1.00	135.80	30.00	95.06
50	6	L42611-48851 WHEEL, DISC	1.00	4776.80	30.00	3343.76
51	7	L88162-48032 SENSOR, BLIND SPOT	1.00	3394.60	30.00	2376.22

Rasul
Ap 90010068
11 days
14/08/24
EXCESS TBA
Reverse
Reay by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

Customer's Signature		Charge Summary	
Please acknowledge receipt of vehicle		Total	
_____		32,721.52	
_____		GST 9.00%	
_____		2,944.94	
_____		Less	
_____		0.00	
_____		Amount Due	
_____		35,666.46	

Date: _____
for & on behalf of

Borneo Motors (Singapore) Pte Ltd