



## ESTIMATE

<b>Account Details</b> ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	Account No.	<b>Customer Details</b> Mr Yeo Boon Kwang 60 Pemimpin Terrace Singapore 575967 Mobile: 90108040
	S1000026 / ICECICS	
	Document No.	
	0	
	Document Date	
	20/09/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AGL25R	AWTGZ L2	29/12/2017	SCX0060P	95669	24775	77/OD/SCX0060P
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTJBAMCA102040798	8ARW686428	60	Cheng Wei Ting	26/08/2024	8.00	20/09/2024	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: MPC23A00385000 ACC DATE:24/07/2024 TOW/DRIVE IN:25/07/2024 EXCESS:- DATE-IN:26/08/2024 DATE SURVEY:14/08/2024 NO OF REPAIR DAYS:11 DAYS BY:RASUL - LKK AUTHORISED ON:16/08/2024				50.00
2	B	BP-LAB3 TO CHECK WIRING AND CONDUCT WATER LEAK T EST	BP31			192.00
3	B	BP-LAB3 TO REMOVE AND REINSTALL REAR BUMPER SENS OR TOENABLE FOR THE REPAIR	BP31			192.00
4	B	BP-ECU3 TO RESET ECU & REPROGRAMME	BP64			192.00
5	B	BP-MECH3 TO CONDUCT ADJUSTMENTON ON REAR BLINDSPO T SENSOR	BP64			192.00
6	B	BP-LAB3 TO REMOVE AND REINSTALL REAR SEAT AND IN TERIORUPHOLESTRY TO ENABLE FOR THE REPAIR	BP31			768.00
7	B	BP-MECH3 TO REPLACE TYRE RIM AND CONDUCT WHEEL BA LANCING	BP64			192.00
8	B	BP-MECH3 TO CONDUCT WHEEL ALIGNMENT ADJUSTMENT	BP64			192.00
9	B	BP-WS3 RENEW REAR RHS QUATER GLASS	BP31			384.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due



## ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	Mr Yeo Boon Kwang 60 Pemimpin Terrace Singapore 575967  Mobile: 90108040
	Document No. 0	
	Document Date 20/09/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AGL25R	AWTGZ L2	29/12/2017	SCX0060P	95669	24775	77/OD/SCX0060P
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTJBAMCA102040798	8ARW686428	60	Cheng Wei Ting	26/08/2024 8.00	20/09/2024 18.00		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	S	BP-SUBLET TO SUPPLY & INSTALL QUATER GLASS 3M SOLA R FILM	0650			230.00
11	B	BP-LAB3 TO REMOVE AND REINSTALL BOTH RHS'S DOOR COMPONENTAND MECHANISM TO NEW DOOR	BP31			1536.00
12	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00
13	B	BP-LAB3 TO REPLACE AND REPAIR ON ACCIDENT AFFECT ED AREA	BP31			4608.00
14	B	BP-RES3 TO SPRAY PAINTING ON ACCIDENT AFFECTED A REA	*			1958.40
15	1	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	1.00	108.00	30.00	75.60
16	2	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00	30.00	140.00
17	3	T08826-08115 PANEL BONDING AD	1.00	267.20	30.00	187.04
18	4	L90269-04051 RIVET	20.00	2.20	30.00	30.80
19	5	T90269-06013 RIVET	20.00	2.80	30.00	39.20
20	6	L67001-48160 PANEL SUB-ASSY, FR	1.00	3614.30	30.00	2530.01
21	7	L67857-48032 PROTECTOR, RR DOOR	1.00	200.80	30.00	140.56
22	8	L75071-48100 MOULDING SUB-ASSY,	1.00	761.60	30.00	533.12
23	9	L75873-48020 MOULDING, QUARTER	1.00	97.60	30.00	68.32
24	0	L75755-48040 MOULDING, FR DOOR	1.00	104.30	30.00	73.01
25	1	L75987-48070 STRIPE, RR DOOR,	1.00	60.60	30.00	42.42

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due



## ESTIMATE

<b>Account Details</b> ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	<b>Account No.</b> S1000026 / ICECICS	<b>Customer Details</b> Mr Yeo Boon Kwang 60 Pemimpin Terrace Singapore 575967 Mobile: 90108040
	<b>Document No.</b> 0	
	<b>Document Date</b> 20/09/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AGL25R	AWTGZ L2	29/12/2017	SCX0060P	95669	24775	77/OD/SCX0060P
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTJBAMCA102040798	8ARW686428	60	Cheng Wei Ting	26/08/2024 8.00	20/09/2024 18.00		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
26	2	L75985-48050 STRIPE, FR DOOR,	1.00	95.60	30.00	66.92
27	3	L75977-48050 STRIPE, RR DOOR,	1.00	45.80	30.00	32.06
28	4	L75965-48010 STRIPE, FR DOOR	1.00	38.00	30.00	26.60
29	5	L75953-48030 TAPE, BLACK OUT RR	1.00	52.80	30.00	36.96
30	6	L75921-48060 TAPE, BLACK OUT,	1.00	23.10	30.00	16.17
31	7	L75707-48030 MOULDING SUB-ASSY,	1.00	135.80	30.00	95.06
32	8	L75605-48020 MOULDING SUB-ASSY,	1.00	194.10	30.00	135.87
33	9	L75077-48010 MOULDING SUB-ASSY,	1.00	126.20	30.00	88.34
34	0	L75075-48140 MOULDING SUB-ASSY,	1.00	600.20	30.00	420.14
35	1	L67895-48041 WEATHERSTRIP, RR	1.00	58.10	30.00	40.67
36	2	L67003-48190 PANEL SUB-ASSY, RR	1.00	3194.80	30.00	2236.36
37	3	L61601-48050 PANEL SUB-ASSY,	1.00	2639.00	30.00	1847.30
38	4	L62710-48310 WINDOW ASSY,	1.00	392.80	30.00	274.96
39	5	L42611-48851 WHEEL, DISC	1.00	4776.80	30.00	3343.76

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total 23,407.65
	Please acknowledge receipt of vehicle	Parts 12,521.25 Labour 10,656.40 Sublet 230.00 Lubrication/Fluid 0.00 Others 0.00	GST 9.00% 2,106.69 Less 0.00 Amount Due 25,514.34