

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
To Inspect Vehicle No: SCX 60P  
at Workshop m/s: RORNB  
of: PANDAN CRESCENT  
Insured: ICS  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: TBA  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition) 11.30  
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 123k  
IDAC Accident Report: Consistent?: Yes or No  
GIA / PR Seent: Consistent?: Yes or No  
Est. Repairs: days Res.: Yes or No  
Lum Sum: % 3 Val: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT

Veh No: SCX 60P Yr Regn: 2017, DBC  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: LEXUS RX200T LUX S/R c.c. 1998  
Colour: GRAY AC: Insured / Std / NI / NA  
Sp. Reading: 95282 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: JTJBMCA102040798  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Modi: Nil / SRim / STD ARim or  
Tyre Size: F: 235/55R20  
R: u a  
BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 24/07/24 D.O.I. 14/08/24  
Survey held at: PANDAN C  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
O/S REAR  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
REPAIR LIMIT - 59K

Date/Time, File Pass to?  : Prell. Report  
 : Final Report  
1) \_\_\_\_\_  
Date/Time, File Return to? \_\_\_\_\_  
2) \_\_\_\_\_  
Report Format : \_\_\_\_\_  
Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_  
Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_  
Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)  
S + RS \_\_\_\_\_ \$  
Photos \_\_\_\_\_  
Others \_\_\_\_\_  
TOTAL



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No.2 Pandan Crescent  
Singapore 128462, Tel no.: 6631 1388



## ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	Mr Yeo Boon Kwang 60 Pemimpin Terrace Singapore 575967  Mobile: 90108040
	Document No. 0	
	Document Date 13/08/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AGL25R	AWTGZ L2	29/12/2017	SCX0060P	0	24775	77/OD/SCX0060P
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTJBAMCA102040798	8ARW686428	60	Cheng Wei Ting	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: MPC23A00385000 ACC DATE:24/07/2024 TOW/DRIVE IN:25/07/2024 EXCESS:500.00\$ DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				<del>50</del> 100.00
2	B	BP-LAB3 TO CHECK WIRING AND CONDUCT WATER LEAK TEST				192.00 ✓
3	B	BP-LAB3 TO REMOVE AND REINSTALL REAR BUMPER SENS OR TOENABLE FOR THE REPAIR				192.00 ✓
4	B	BP-ECU3 TO RESET ECU & REPROGRAMME				192.00 ✓
5	B	BP-MECH3 TO CONDUCT ADJUSTMENTON ON REAR BLINDSPOT SENSOR				192.00 ✓
6	B	BP-LAB3 TO REMOVE AND REINSTALL REAR SEAT AND INTERIORUPHOLESTRY TO ENABLE FOR THE REPAIR				768.00 ✓
7	B	BP-MECH3 TO REPLACE TYRE RIM AND CONDUCT WHEEL BALANCING				192.00 ✓
8	B	BP-MECH3 TO CONDUCT WHEEL ALIGNMENT ADJUSTMENT				192.00 ✓
9	B	BP-WS3 RENEW REAR RHS QUATER GLASS				384.00 ✓

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due



Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No.2 Pandan Crescent  
Singapore 128462, Tel no.: 6631 1388

## ESTIMATE

Account Details			Account No.		Customer Details		
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987			S1000026 / ICECICS		Mr Yeo Boon Kwang		
			Document No. 0		60 Pemimpin Terrace		
			Document Date 13/08/2024		Singapore 575967  Mobile: 90108040		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AGL25R	AWTGZ L2	29/12/2017	SCX0060P	0	24775	77/OD/SCX0060P
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTJBAMCA102040798		8ARW686428	60	Cheng Wei Ting	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
10	S	BP-SUBLET TO SUPPLY & INSTALL QUATER GLASS 3M SOLA R FILM					230.00
11	B	BP-LAB3 TO REMOVE AND REINSTALL BOTH RHS'S DOOR COMPONENTAND MECHANISM TO NEW DOOR					1536.00
12	Z	BP-SLANT SUPPLY SEALANT (NETT)					200.00
13	B	BP-LAB3 TO REPLACE AND REPAIR ON ACCIDENT AFFECT ED AREA					6144.00
14	B	BP-RES3 TO SPRAY PAINTING ON ACCIDENT AFFECTED A REA					3916.80
15	1	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	1.00	108.00	30.00		75.60
16	2	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00	30.00		140.00
17	3	T08826-08115 PANEL BONDING AD	1.00	267.20	30.00		187.04
18	4	L90269-04051 RIVET	20.00	2.20	30.00		30.80
19	5	T90269-06013 RIVET	20.00	2.80	30.00		39.20
20	6	L52159-48931 COVER, RR BUMPER	1.00	1582.60	30.00		1107.82
21	7	L61601-48050 PANEL SUB-ASSY,	1.00	2639.00	30.00		1847.30
22	8	L65637-48070 LINER, RR WHEEL	1.00	493.60	30.00		345.52
23	9	L62904-48030 DUCT SUB-ASSY,	1.00	213.20	30.00		149.24
24	0	L62710-48310 WINDOW ASSY,	1.00	392.80	30.00		274.96
25	1	L67001-48160 PANEL SUB-ASSY, FR	1.00	3614.30	30.00		2530.01
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due



Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No.2 Pandan Crescent  
Singapore 128462, Tel no.: 6631 1388

## ESTIMATE

Account Details			Account No.		Customer Details				
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987			S1000026 / ICECICS		Mr Yeo Boon Kwang 60 Pemimpin Terrace Singapore 575967 Mobile: 90108040				
			Document No. 0						
			Document Date 13/08/2024						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	AGL25R	AWTGZ L2	29/12/2017	SCX0060P	0	24775	77/OD/SCX0060P		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTJBAMCA102040798		8ARW686428	60	Cheng Wei Ting	--/--/----		0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
26	2	L67861-48110	WEATHERSTRIP, FR <del>X</del>			1.00	392.80	30.00	274.96
27	3	L75921-48060	TAPE, BLACK OUT, <del>nu</del>			1.00	23.10	30.00	16.17
28	4	L75985-48050	STRIPE, FR DOOR, <del>nu</del>			1.00	95.60	30.00	66.92
29	5	L75965-48010	STRIPE, FR DOOR <del>nu</del>			1.00	38.00	30.00	26.60
30	6	L68610-48080	CHECK ASSY, FR DOOR, <del>X</del>			1.00	381.60	30.00	267.12
31	7	L67003-48190	PANEL SUB-ASSY, RR <del>bt</del>			1.00	3194.80	30.00	2236.36
32	8	L67871-48080	WEATHERSTRIP, RR <del>X</del>			1.00	347.00	30.00	242.90
33	9	L75977-48050	STRIPE, RR DOOR, <del>nu</del>			1.00	45.80	30.00	32.06
34	0	L75987-48070	STRIPE, RR DOOR, <del>nu</del>			1.00	60.60	30.00	42.42
35	1	L75953-48030	TAPE, BLACK OUT RR <del>nu</del>			1.00	52.80	30.00	36.96
36	2	L67895-48041	WEATHERSTRIP, RR <del>nu</del>			1.00	58.10	30.00	40.67
37	3	L67857-48032	PROTECTOR, RR DOOR <del>su</del>			1.00	200.80	30.00	140.56
38	4	L68630-48080	CHECK ASSY, RR DOOR <del>X</del>			1.00	381.60	30.00	267.12
39	5	L75071-48100	MOULDING SUB-ASSY, <del>su</del>			1.00	761.60	30.00	533.12
40	6	L75075-48140	MOULDING SUB-ASSY, <del>su</del>			1.00	600.20	30.00	420.14
41	7	L75077-48010	MOULDING SUB-ASSY, <del>su</del>			1.00	126.20	30.00	88.34
42	8	L75605-48020	MOULDING SUB-ASSY, <del>su</del>			1.00	194.10	30.00	135.87
43	9	L75873-48020	MOULDING, QUARTER <del>nu</del>			1.00	97.60	30.00	68.32
44	0	L75850-48040	MOULDING ASSY, BODY <del>X</del>			1.00	761.60	30.00	533.12
45	1	L75867-30120	CLIP, ROCKER PANEL <del>X</del>			14.00	15.10	30.00	147.98
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total		
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		



## ESTIMATE

Account Details		Account No.	Customer Details	
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	Mr Yeo Boon Kwang	
		Document No. 0	60 Pemimpin Terrace	
		Document Date 13/08/2024	Singapore 575967 Mobile: 90108040	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AGL25R	AWTGZ L2	29/12/2017	SCX0060P	0	24775	77/OD/SCX0060P
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTJBAMCA102040798	8ARW686428	60	Cheng Wei Ting	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
46	2	L75857-48010 COVER, ROCKER PANEL X	4.00	5.40	30.00	15.12
47	3	L75865-48040 PROTECTOR, ROCKER X	1.00	60.50	30.00	42.35
48	4	L75755-48040 MOULDING, FR DOOR X	1.00	104.30	30.00	73.01
49	5	L75707-48030 MOULDING SUB-ASSY, X	1.00	135.80	30.00	95.06
50	6	L42611-48851 WHEEL, DISC SW	1.00	4776.80	30.00	3343.76
51	7	L88162-48032 SENSOR, BLIND SPOT	1.00	3394.60	30.00	2376.22

*Repair*  
*to 90010068*  
*11 days*  
*14/08/24*  
*EXCESS: TBA*  
*Repair*  
*Regr by paint*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature Please acknowledge receipt of vehicle	Charge Summary	Total	32,721.52
		Parts 18,290.72	GST 9.00%	2,944.94
		Labour 14,200.80	Less	0.00
		Sublet 230.00	Amount Due	35,666.46
		Lubrication/Fluid 0.00		
		Others 0.00		

> **Back to OneMotoring**

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	822Z
<b>Vehicle Details</b>	
Vehicle No.:	SCX60P
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Aug 2024
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS RX200T LUXURY AT S/R
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	8ARW686428
Chassis No.:	JTJBAMCA102040798
Maximum Power Output:	175.0 kW (234 bhp)
Open Market Value:	\$56,222.00
Original Registration Date:	29 Dec 2017
First Registration Date:	29 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$73,200.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2027
PARF Rebate Amount:	\$47,580.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	28 Dec 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,011.00
COE Rebate Amount:	\$15,844.00
<b>Total Rebate Amount:</b>	<b>\$63,424.00</b>
<b>Message</b>	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 14 Aug 2024

OK



# Lexus RX Turbo RX200t Luxury Sunroof

**\$123,000** Instalment \$2,386/mth

PREMIUM AD

Apply for 2.48% loan

Shortlist

Get Warranty



## Overview

## Financial

## Leasing

## Photo

## Research

Depreciation

\$25,620 / year

Reg. Date

29-Dec-2017

(3yrs 4mths 14days COE left)

Manufactured

2017

Mileage

100,300 km (15.1k / year)

Transmission

Auto

Engine Cap

1,998 cc

Road Tax

\$1,210 / year

Power

175.0 kW (234 bhp)

Curb Weight

2,070 kg

COE

\$53,711

OMV

\$56,222

ARF

\$73,200

Dereg Value

\$65,695 as of today

No. of Owners

4