



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24060103/Kvh3e2
16 RAFFLES QUAY	Date:	14/06/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 2480J	Veh. Inspected	SHB 9529C
Policy No.	-	Coverage	0
Claim No.	D24005266MFCT	Excess	\$0.00
Assign From	AINI	Assign Date	14/06/2024

### 2. Vehicle Details

Make & Model	TOYOTA PRIUS (A)	C.C	1798
Engine No.	2ZR2C43480	Year of Reg.	16/08/2019
Chassis No.	JTDKB3FUX03082736	Colour	METALLIC PEARL WHITE / RED
Odometer	519783 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	SAILUN	9
L/H Front Tyre	195/65R15	SAILUN	9
R/H Rear Tyre	195/65R15	SAILUN	8
L/H Rear Tyre	195/65R15	SAILUN	8

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR MIRROR.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	08/06/2024	Inspection Date	14/06/2024
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days