

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

TO	: LIBERTY	DATE	14/8/2024
VEHICLE NO	: SGY800T (2017)		Veron.
VEHICLE MODEL	: HONDA SHUTTLE		
CHASSIS NO	: GK81004114		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Dehd</i>	1	\$ 986.90	\$ 986.90
2	REAR BUMPER REFLECTOR <i>Nbr new</i>	2	\$ 45.20	\$ 90.40
3	REAR BUMPER REFLECTOR GARNISH <i>Torn</i>	2	\$ 45.40	\$ 90.80
4	REAR BUMPER TOWING COVER <i>Nbr new</i>	1	\$ 19.00	\$ 19.00
5	REAR BUMPER SIDE RETAINER <i>Nbr new</i>	2	\$ 32.00	\$ 64.00
6	REAR BUMPER SIDE SPONGE <i>Cracked</i>	2	\$ 47.00	\$ 94.00
7	TAILGATE <i>Dehd</i>	1	\$ 1,193.20	\$ 1,193.20
8	TAILGATE OUTER CHROME MOULDING <i>Nbr new</i>	1	\$ 383.80	\$ 383.80
9	TAILGATE LOGO <i>Nbr new</i>	1	\$ 38.40	\$ 38.40
10	TAILGATE SHUTTLE EMBLEM <i>Nbr new</i>	1	\$ 55.40	\$ 55.40
11	TAILGATE LAMP <i>Nbr new</i>	2	\$ 380.90	\$ 761.80
12	TAILGATE INNER LOCK <i>Damaged</i>	1	\$ 298.40	\$ 298.40
13	TAILGATE LOCK CATCH <i>Nbr new</i>	1	\$ 24.00	\$ 24.00
14	TAILGATE WEATHERSTRIP <i>Nbr new</i>	1	\$ 166.50	\$ 166.50
15	TAILGATE LOCK ANTENNA <i>Nbr new</i>	1	\$ 180.20	\$ 180.20
16	TAILGATE INNER TRIM BOARD <i>Cracked</i>	1	\$ 320.40	\$ 320.40
17	TAILGATE WINDSCREEN MOULDING <i>Nbr new</i>	1	\$ 149.20	\$ 149.20
18	TAILGATE BUZZER <i>Nbr new</i>	1	\$ 170.00	\$ 170.00
19	TAILLAMP <i>Nbr new</i>	2	\$ 520.50	\$ 1,041.00
20	REAR END PANEL <i>Dehd</i>	1	\$ 681.20	\$ 681.20
21	REAR END PANEL TOP GARNISH <i>Dehd</i>	1	\$ 155.00	\$ 155.00
22	REAR FLOOR PANEL TOP OUTER BOARD <i>Nbr new</i>	1	\$ 585.20	\$ 585.20
23	REAR PLASTIC STROAGE BOX <i>Cracked</i>	1	\$ 495.00	\$ 495.00
24	REAR TOOLS SPONGE TRAY <i>Nbr new</i>	1	\$ 165.40	\$ 165.40
25	REAR JACK COVER <i>Nbr new</i>	1	\$ 122.40	\$ 122.40

TOTAL PRICE: \$ 8,331.60

LESS 20% \$ 1,666.32

SUB TOTAL PRICE: \$ 6,665.28

4486

358880

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE HOLDER <i>Dehd</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER CLIPS (SET) <i>Nbr new</i>	1	\$ 50.00	\$ 50.00
4	TAILGATE OUTER CHROME MOULDING CLIPS (SET) <i>Nbr new</i>	1	\$ 30.00	\$ 30.00
5	TAILGATE WINDSCREEN SEALANT <i>Nbr new</i>	1	\$ 60.00	\$ 60.00
6	TAILLAMP CLIPS (SET) <i>Nbr new</i>	1	\$ 20.00	\$ 20.00
7	REAR END PANEL SEALANT <i>Nbr new</i>	1	\$ 60.00	\$ 60.00
8	REAR END PANEL TOP GARNISH CLIPS (SET) <i>Nbr new</i>	1	\$ 20.00	\$ 20.00

9	REVERSE SENSOR (SET) <i>new</i>	1	\$ 280.00	\$ 280.00	x
10	REAR CAMERA <i>new</i>	1	\$ 480.00	\$ 480.00	x
			TOTAL :	\$ 1,000.00	230

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	70	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	70	
3	WIRING CHECK	\$ 50.00	30	
4	TUFF COAT	\$ 150.00	60	
5	TO REMOVE UPHOLSTERY	\$ 150.00	60	
6	TO REMOVE TAILGATE GLASS	\$ 180.00	120	
7	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	60	
8	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
9	TO REMOVER REAR CAMERA	\$ 100.00	50	
		TOTAL \$	3 280.00	

ESTIMATE REPORT

TOTAL PARTS COST: \$ 7,665.28
 TOTAL LABOUR COST: \$ 3,280.00
 TOTAL REPAIR COST: \$ 10,945.28

total: 5648.80

L/S: 4.51c

062 up

4.51c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: