

# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

## CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road  
Springleaf Tower #16-00  
Singapore 079909

Tel: 63896111 Fax: 6221033  
Attn: Motor Claim Department \ CHINA  
TAIPING

Your Ref No: TP 0824-8191  
Claim Type: Third Party  
Accident Date: 10 August 2024  
TP Veh Reg No: GBK2953E

*Not Authorized  
2/9/24  
2/s # 4400  
Chap. 4400  
H. 4400*

Estimate No: **EST1511642**  
Date: 12 Aug 2024  
Policy No: MT/01498518  
Veh Reg No: SLM8403H  
Make/Model: TOYOTA COROLLA  
ALTIS 1.6 CVT  
Chassis No: MR053REH104560879  
Engine No: 1ZRY341825  
Reg. Date: 13 Apr 2017

### Estimate Repair Cost to Vehicle No: SLM8403H

| Description                                 | Unit Price | Quantity          | List Price<br>SGD | Amount<br>SGD |
|---------------------------------------------|------------|-------------------|-------------------|---------------|
| <b>List Price</b>                           |            |                   |                   |               |
| 1 REAR BUMPER                               | 828.80     | 1 PC <i>20/12</i> | 828.80            | —             |
| 2 REAR BUMPER SIDE RETAINER - LH/RH         | 164.40     | 2 PC <i>17</i>    | 328.80            | X             |
| 3 REAR BUMPER CLIPS                         | 5.50       | 10 PC <i>20</i>   | 55.00             | —             |
| 4 REAR BUMPER REINFORCEMENT                 | 598.20     | 1 PC <i>100</i>   | 598.20            | —             |
| 5 REAR BUMPER REINFORCEMENT BRACKET - LH/RH | 92.50      | 2 PC <i>17</i>    | 185.00            | X             |
| 6 REAR BUMPER REFLECTOR - LH/RH             | 81.80      | 2 PC <i>17</i>    | 163.60            | X             |
| 7 REAR END PANEL                            | 1,008.40   | 1 PC <i>20/12</i> | 1,008.40          | —             |
| 8 REAR END PANEL TOP GARNISH                | 327.80     | 1 PC <i>400</i>   | 327.80            | —             |
| 9 REAR BOOT                                 | 1,294.40   | 1 PC <i>12</i>    | 1,294.40          | X             |
| 10 REAR BOOT HINGE - LH/RH                  | 94.80      | 2 PC <i>800</i>   | 189.60            | X             |
| 11 REAR BOOT LAMP - LH/RH <i>\$ 299.20</i>  | 799.20     | 2 PC <i>0/500</i> | 1,598.40          | 120           |
| 12 REAR BOOT OUTER CHROME                   | 330.80     | 1 PC <i>500</i>   | 330.80            | —             |
| 13 REAR BOOT "COROLLA" WORDINGS             | 65.70      | 1 PC <i>100</i>   | 65.70             | —             |
| 14 REAR BOOT "ALTIS" WORDINGS               | 70.80      | 1 PC <i>100</i>   | 70.80             | —             |
| 15 REAR BOOT TOYOTA LOGO                    | 72.70      | 1 PC <i>100</i>   | 72.70             | —             |
| 16 REAR BOOT RUBBER                         | 238.20     | 1 PC <i>Torn</i>  | 238.20            | —             |
| 17 REAR BOOT TOP LOCK                       | 542.40     | 1 PC <i>800</i>   | 542.40            | X             |
| 18 REAR BOOT LOWER LOCK STRIKER             | 80.60      | 1 PC <i>17</i>    | 80.60             | X             |
| 19 REAR BOOT NUMBER PLATE LAMP - LH/RH      | 89.20      | 2 PC <i>17</i>    | 178.40            | X             |
| 20 REAR BOOT INNER TRIM CLIPS               | 5.50       | 10 PC <i>17</i>   | 55.00             | X             |
| 21 TAILLAMP - LH/RH                         | 402.80     | 2 PC <i>100</i>   | 805.60            | —             |
| 22 TAILLAMP CLIPS - LH/RH                   | 5.50       | 2 PC <i>17</i>    | 11.00             | X             |

rear antenna sensor 266.20 *Done*

# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@proccare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

|          |           |          |
|----------|-----------|----------|
|          | 9,029.20  |          |
| Less 25% | -2,257.00 | 6,772.20 |

## Special Net

|    |                               |        |      |        |        |        |
|----|-------------------------------|--------|------|--------|--------|--------|
| 23 | REAR NUMBER PLATE WITH CASING | 35.00  | 1 PC | 17     | 35.00  | X      |
| 24 | REAR BUMPER SENSOR            | 200.00 | 1 PC | 100.00 | 200.00 | 200    |
| 25 | REAR REVERSE CAMERA           | 350.00 | 1 PC | 17     | 350.00 | X      |
|    |                               |        |      |        |        | 585.00 |

## Labour

|    |                                                       |        |      |  |        |          |
|----|-------------------------------------------------------|--------|------|--|--------|----------|
| 26 | TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PORTIONS | 900.00 | 1 PC |  | 900.00 | 600      |
| 27 | TO RESPRAY PAINT ON ACCIDENT PORTIONS                 | 900.00 | 1 PC |  | 900.00 | 800      |
| 28 | TO CHECK WIRING                                       | 50.00  | 1 PC |  | 50.00  | 20       |
| 29 | TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR         | 150.00 | 1 PC |  | 150.00 | 60       |
| 30 | TO REMOVE, REPLACE REAR BUMPER SENSOR                 | 80.00  | 1 PC |  | 80.00  | 30       |
| 31 | TO TRANSFER REAR BOOT FITTINGS                        | 80.00  | 1 PC |  | 80.00  | 50       |
| 32 | TO TUFFKOTE                                           | 90.00  | 1 PC |  | 90.00  | 50       |
|    |                                                       |        |      |  |        | 2,250.00 |

|                          |           |
|--------------------------|-----------|
| Total                    | 9,607.20  |
| Add GST @ 9%             | 864.65    |
| Total Amount Payable SGD | 10,471.85 |

**SINGAPORE DOLLAR TEN THOUSAND FOUR HUNDRED SEVENTY ONE AND CENTS EIGHTY FIVE ONLY**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE