

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road
Springleaf Tower #16-00
Singapore 079909

Tel: 63896111 Fax: 6221033
Attn: Motor Claim Department \ CHINA
TAIPING

Your Ref No: TP 0824-8191
Claim Type: Third Party
Accident Date: 10 August 2024
TP Veh Reg No: GBK2953E

*Not Authorized
mercy
2/9/24
2/5 # 4400
ahpbe. ste m
H dngs*

Estimate No: **EST1511642**
Date: 12 Aug 2024
Policy No: MT/01498518
Veh Reg No: SLM8403H
Make/Model: TOYOTA COROLLA
ALTIS 1.6 CVT
Chassis No: MR053REH104560879
Engine No: 1ZRY341825
Reg. Date: 13 Apr 2017

Estimate Repair Cost to Vehicle No: SLM8403H

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 REAR BUMPER	828.80	1 PC <i>20/12</i>	828.80	—
2 REAR BUMPER SIDE RETAINER - LH/RH	164.40	2 PC <i>17</i>	328.80	X
3 REAR BUMPER CLIPS	5.50	10 PC <i>mer</i>	55.00	—
4 REAR BUMPER REINFORCEMENT	598.20	1 PC <i>10</i>	598.20	—
5 REAR BUMPER REINFORCEMENT BRACKET - LH/RH	92.50	2 PC <i>17</i>	185.00	X
6 REAR BUMPER REFLECTOR - LH/RH	81.80	2 PC <i>17</i>	163.60	X
7 REAR END PANEL	1,008.40	1 PC <i>20/12</i>	1,008.40	—
8 REAR END PANEL TOP GARNISH	327.80	1 PC <i>17</i>	327.80	—
9 REAR BOOT	1,294.40	1 PC <i>17</i>	1,294.40	X
10 REAR BOOT HINGE - LH/RH	94.80	2 PC <i>50</i>	189.60	X
11 REAR BOOT LAMP - LH/RH	<i>299.20</i> 799.20	2 PC <i>0/50</i>	1,598.40	1 PC
12 REAR BOOT OUTER CHROME	330.80	1 PC <i>50</i>	330.80	—
13 REAR BOOT "COROLLA" WORDINGS	65.70	1 PC <i>17</i>	65.70	—
14 REAR BOOT "ALTIS" WORDINGS	70.80	1 PC <i>17</i>	70.80	—
15 REAR BOOT TOYOTA LOGO	72.70	1 PC <i>17</i>	72.70	—
16 REAR BOOT RUBBER	238.20	1 PC <i>Torn</i>	238.20	—
17 REAR BOOT TOP LOCK	542.40	1 PC <i>50</i>	542.40	X
18 REAR BOOT LOWER LOCK STRIKER	80.60	1 PC <i>17</i>	80.60	X
19 REAR BOOT NUMBER PLATE LAMP - LH/RH	89.20	2 PC <i>17</i>	178.40	X
20 REAR BOOT INNER TRIM CLIPS	5.50	10 PC <i>17</i>	55.00	X
21 TAILLAMP - LH/RH	402.80	2 PC <i>one</i>	805.60	—
22 TAILLAMP CLIPS - LH/RH	5.50	2 PC <i>17</i>	11.00	X

rear antenna sensor 266.20 done ✓

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@proccarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

	9,029.20	
Less 25%	-2,257.00	6,772.20

Special Net

23	REAR NUMBER PLATE WITH CASING	35.00	1 PC	17	35.00	X
24	REAR BUMPER SENSOR	200.00	1 PC	1 set modification	200.00	200
25	REAR REVERSE CAMERA	350.00	1 PC	17	350.00	X
						585.00

Labour

26	TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PORTIONS	900.00	1 PC		900.00	600
27	TO RESPRAY PAINT ON ACCIDENT PORTIONS	900.00	1 PC		900.00	800
28	TO CHECK WIRING	50.00	1 PC		50.00	20
29	TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR	150.00	1 PC		150.00	60
30	TO REMOVE, REPLACE REAR BUMPER SENSOR	80.00	1 PC		80.00	30
31	TO TRANSFER REAR BOOT FITTINGS	80.00	1 PC		80.00	50
32	TO TUFFKOTE	90.00	1 PC		90.00	50
						2,250.00

Total	9,607.20
Add GST @ 9%	864.65
Total Amount Payable SGD	10,471.85

SINGAPORE DOLLAR TEN THOUSAND FOUR HUNDRED SEVENTY ONE AND CENTS EIGHTY FIVE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road

Springleaf Tower #16-00

Singapore 079909

Tel: 63896111

Fax: 6221033

Attn: Motor Claim Department \ CHINA
TAIPING

Your Ref No: TP 0824-8191

Claim Type: Third Party

Accident Date: 10 August 2024

TP Veh Reg No: GBK2953E

Estimate No: EST1511642

Date: 11 Sep 2024

Policy No: MT/01498518

Veh Reg No: SLM8403H

Make/Model: TOYOTA COROLLA

ALTIS 1.6 CVT

Chassis No: MR053REH104560879

Engine No: 1ZRY341825

Reg. Date: 13 Apr 2017

Estimate Repair Cost to Vehicle No: SLM8403H

Description	Unit Price	Quantity	List Price SGD	Amount SGD
Supplementary Parts to Repair List Price				
1 REAR KEY ANTENNA	266.20	1 PC <i>key</i>	266.20	
			266.20	
		Less 25%	-66.60	199.60

Total 199.60

Add GST @ 9% 17.96

Total Amount Payable SGD 217.56

SINGAPORE DOLLAR TWO HUNDRED SEVENTEEN AND CENTS FIFTY SIX ONLY

supp 199.60

parts 3535.90

SN 200.00

LAB 1610.00

5545.50

Ys: 4400

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE