

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 11 Sep 2024

Preliminary Advice

Insured Vehicle No	: FBQ2165G		
TP Vehicle No	: SLV6382A	Accident Date	: 02/08/2024
Make	: NISSAN QASHQAI	Assignment Date	: 13/08/2024
Date of Inspection	: 06/09/2024	Est. Duration of Repair	: 2
Inspection At	: ACCORD AUTO SERVICES PTE LTD (HQ) 10 ANG MO KIO IND PARK 2A #03-11, AMK AUTO POINT SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,163.69
Revised Amount	:S\$	1,312.76
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,312.76
 Lump Sum Repair	 :S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (x) Lump Sum repair
- (x) The above survey was conducted on a 'without prejudice' basis.
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.